



**MODEL ANSWER**

WINTER- 17 EXAMINATION

**Subject Title: Automobile Manufacturing Processes**

**Subject Code: 17403**

**Important Instructions to examiners:**

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more Importance (Not applicable for subject English and Communication Skills).
- 4) While assessing figures, examiner may give credit for principal components indicated in the figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case of some questions credit may be given by judgement on part of examiner of relevant answer based on candidate's understanding.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.

Q. No.	Sub Q. N.	Answer	Marking Scheme
1a)		<b>Attempt any SIX of the following</b>	<b>12</b>
1a)	i)	<b>Enlist any four forging components.</b>	<b>02</b>
	<b>Ans:</b>	<b>Forging Components:</b> (Any 4 suitable components , ½ mark each) 1. Connecting rod 2. Crankshaft 3. Camshaft 4. Alloy wheel 5. Drive shafts 6. Clutch hubs 7. Universal joints 8. Hand Tools	<b>02</b>
1a)	ii)	<b>Enlist any four pressing operations.</b>	<b>02</b>
	<b>Ans:</b>	Pressing Operations are as follows (Any four 2 marks: ½ mark each) a) Blanking b) Punching c) Notching d) Perforating e) Trimming f) Shaving g) Slitting h) Lancing i) Bending j) Drawing k) Squeezing	<b>02</b>





		<b>f. Electron Beam Welding (EBW)</b> <b>g. Laser Welding (LW)</b>	
<b>1a)</b>	<b>v)</b>	<b>List any four factors affecting selection of surface finishing processes.</b>	<b>02</b>
	<b>Ans:</b>	Following factors will affect the selection of surface finishing processes: ( ½ Mark Each) 1. Material of component 2. Basic machining operation carried out on component 3. Dimensions of component 4. Final value (in µm) of machined surfaces 5. Application of machined surfaces	
<b>1a)</b>	<b>vi)</b>	<b>Give the meaning of following ISO codes.</b> 1) <b>M02</b> 2) <b>M30</b> 3) <b>G90</b> 4) <b>G91</b>	<b>02</b>
	<b>Ans:</b>	Meaning of ISO codes.( ½ Mark Each) 1) M02-Program end 2) M30-Program stop & Tape rewind 3) G90 :- Absolute Dimensioning 4) G91:- Incremental Dimensioning	<b>02</b>
<b>1a)</b>	<b>vii)</b>	<b>Define NC and CNC machine.</b>	<b>02</b>
	<b>Ans:</b>	Definition - (1 mark each) <b>NC Machine:</b> “A system in which actions are controlled by direct insertions of numerical data at some point.” or In simple words, “Numerical Control Machines means machine controlled by number’s programme” or “It is a programmable automation in which actions are controlled by means of numbers, letters, & other symbols.” <b>CNC Machine:</b> It is computer numerical control in which a dedicated computer is used to perform all the basic NC functions.	<b>01</b>      <b>01</b>
<b>1a)</b>	<b>viii)</b>	<b>Give any four advantages of forging processes.</b>	<b>02</b>
	<b>Ans:</b>	<b>Advantages of forging processes:</b> (Any Four – ½ Mark Each) 1) Complex shaped parts can be forged 2) Mass production with greater accuracy is achieved. 3) It is very easy to maintain close tolerances. 4) Does not require highly skilled operator. 5) Better reproducibility. 6) Machining is not necessary to obtain final shape	<b>02</b>
<b>1</b>	<b>B</b>	<b>Attempt any TWO of the following</b>	<b>08</b>
<b>1b)</b>	<b>i)</b>	<b>Define forgeability and give any four forgeable materials used to produce automotive components.</b>	<b>04</b>



**MODEL ANSWER**






WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

	<p><b>Ans:</b> <b>Forgeability</b> (Definition 2 mark) Forgeability can be defined as the tolerance of a metal or alloy for deformation without failure.</p> <p style="text-align: center;">OR</p> <p>Forgeability is defined as the ability of a metal to change size and shape when heated to required temperature and compressed by applying some pressure.</p> <p><b>Forgeable Materials: (Any Four : ½ Mark each)</b></p> <ol style="list-style-type: none"> <li>1) Aluminum alloys</li> <li>2) Magnesium alloys</li> <li>3) Copper alloys.</li> <li>4) Carbon and low alloy steels</li> <li>5) Martensitic stainless steels</li> <li>6) Austenitic stainless steels</li> <li>7) Nickel alloys</li> <li>8) Titanium alloys</li> <li>9) Columbium alloys</li> <li>10) Tantalum alloys</li> <li>11) Molybdenum alloys</li> <li>12) Tungsten alloys</li> <li>13) Beryllium.</li> </ol>	<p style="text-align: right;"><b>02</b></p> <p style="text-align: right;"><b>02</b></p>
<p><b>1b)</b></p>	<p><b>ii)</b> <b>Enlist any four operations carried out in forging process and explain fullering with neat sketch.</b></p>	<p style="text-align: right;"><b>04</b></p>
	<p><b>Ans:</b> <b>Operations carried out in forging process:</b> ( any four operations: ½ mark each, sketch 1mark and explanation 1mark)</p> <ol style="list-style-type: none"> <li>a) Upsetting</li> <li>b) Drawing Down</li> <li>c) Setting down</li> <li>d) Welding</li> <li>e) Bending</li> <li>f) Cutting</li> <li>g) Punching</li> </ol> <p><b>Fullering:</b></p> <div style="text-align: center;"> </div> <p>In fullering, the material cross section is decreased and length is increased. Figure shows that the bottom fuller is kept in the anvil hole with the heated stock over the fuller. The top fuller is then kept above the stock and then with the sledge hammer. The force is applied on the top fuller which results in decreasing the</p>	<p style="text-align: right;"><b>02</b></p> <p style="text-align: right;"><b>01</b></p> <p style="text-align: right;"><b>01</b></p>



		cross section at that point.	
<b>1b</b>	<b>iii)</b>	<b>State the forging sequence for production of spanner.</b>	<b>04</b>
	Ans:	<p>Forging sequence for production of spanner (Any four steps – 1 Mark Each) Forging Sequence for Spanner:</p> <p>(1) The heated stock is elongated by reducing its cross section in first die. The operation is known as “Fullering”.</p>  <p>(2) The metal is redistributed, increasing the cross section at certain places and reducing at others as required filling the cavities of the die. The operation is known as “Edging”.</p>  <p>(3) General shape is given in first blocking die.</p>  <p>(4) Finished shape is given to forging in final impression die.</p>  <p>(5) Flash is removed.</p>  <p>(6) Heat treatment and machining is done as per requirement.</p>	04
2		<b>Attempt any four of the following :</b>	<b>16</b>
2	a)	<b>Give classification of forging process.</b>	<b>04</b>







**MODEL ANSWER**

WINTER- 17 EXAMINATION


Subject Title: Automobile Manufacturing Processes

Subject Code: 17403


	<p><b>Ans:</b> Classification of forging process -</p> <p>I. Open die forging:</p> <ul style="list-style-type: none"> <li>a) Hand forging</li> <li>b) Power forging:             <ul style="list-style-type: none"> <li>i. Hammer forging</li> <li>ii. Press forging</li> </ul> </li> </ul> <p>II. Close die forging:</p> <ul style="list-style-type: none"> <li>a) Drop forging</li> <li>b) Press forging</li> <li>c) Machine forging</li> </ul> <p style="text-align: center;">OR</p>  <pre> graph TD     Forging --&gt; Open["Open /Smith/Flat Die forging"]     Forging --&gt; Closed["Closed/ Impression Die forging"]     Open --&gt; Hand     Open --&gt; Power     Power --&gt; Hammer     Power --&gt; Press     Closed --&gt; Drop     Closed --&gt; Press     Closed --&gt; Machine             </pre>	<p>04</p> <p>Or</p> <p>04</p>
2	<p><b>b) Explain forging sequence for camshaft.</b></p>	04
	<p>Forging process for manufacturing Camshaft:(Any four steps – 1 Mark Each)</p> <p>i) Stock is redistributed and size is increased at certain places &amp; reduced at others by rolled forging.</p>  <p>ii) after preliminary roll forging, the stock is again roll forged.</p>  <p>iii) This stock is then forged in first impression or blocking die.</p>	04



iv) final shape is given to the forging in next blocking die.



v) finished part is trimmed in blanking die to remove excess metal or flash.



c) Describe fly press with neat sketch.

04

Ans: (02 Marks for Description of Fly press, 02 Marks for Neat Sketch)

**Fly Press :**

- It is simplest type of all presses, called as hand press / ball press/single side fly press.
- It consists of robust cast iron frame. Top portion of frame forms the nut.
- Vertical screw which can go through the nut. Screw carries an arm.
- Arm supports two cast iron weights (balls) at two ends. Handle used for rotating the arm.
- Frame extended below the nut to form guides. Ram attached at the bottom of the screw.
- Ram carries punch at its bottom. Die is fixed at the press base.
- Sheet metal placed over the die. Arm gets quick rotation with the help of handle.
- Heavy balls stores kinetic energy for long time movement of screw.

02


**MODEL ANSWER**

WINTER- 17 EXAMINATION


Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

- Movement of screw causes movement of ram & punch downwards.
- Stroke of the collar adjusted with help of Stop Collar / Arrestor. Advance type of fly press is double side Press.



OR



02







**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

2	d)	<b>Enlist any four die accessories and explain use of stops.</b>	<b>04</b>
	Ans:	<p><b>Die accessories: (any Four ½ mark each)</b></p> <ol style="list-style-type: none"><li>1. Stops</li><li>2. Pilots</li><li>3. Knock Out</li><li>4. Strippers</li><li>5. Pressure pad</li></ol> <p><b>Stops:</b> The stops are used for correct spacing of the sheet metal as it is fed below the punch to give the greatest output in given length of the plate. Button stop and lever stop.</p> <p><b>Button stop:</b> The button stop illustrated in Fig. is the simplest of the designs. A small pin or a button 2 is fixed to the die block 4 at a measured distance from the punch axis. After the end of each cut, the plate 3 is lifted and pushed aside till the edge of the next slot bears against the button 2. This makes the accurate spacing. The button stop is used in hand presses and in slow acting power presses.</p>  <p>1. Punch, 2. Button, 3. Plate, 4. Die block. Figure. Button Stop</p> <p><b>Lever stop:</b> - The lever stop illustrated in Fig., is operated by the machine. As the punch 1 descends, the pin 2 attached to the ram pushes the lever 3 which lifts the lever stop, leaving the blank 4 free. The plate is pushed aside immediately when the punch 1 starts moving in the upward strokes, and in the next instant the lever 3 is released from pin pressure that causes the stop to engage with the work making an accurate spacing.</p>  <p>1. Punch, 2. Pin, 3. Lever, 4. Plate, 5. Die block</p>	02




**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes


Subject Code: 17403

2	e)	<b>Difference between compound and combination die.</b>	<b>04</b>												
	Ans:	<p>Difference between compound and combination die. (Any Four – 1 Mark Each)</p> <table border="1" data-bbox="332 520 1395 1171"> <thead> <tr> <th data-bbox="332 520 865 583">Compound die</th> <th data-bbox="865 520 1395 583">Combination die</th> </tr> </thead> <tbody> <tr> <td data-bbox="332 583 865 726">1. Any two cutting operations can be performed at one station.</td> <td data-bbox="865 583 1395 726">1. Both cutting and forming operations can be performed at one station.</td> </tr> <tr> <td data-bbox="332 726 865 829">2. Both operations performed in a single stroke of press</td> <td data-bbox="865 726 1395 829">2. Two separate strokes of press.</td> </tr> <tr> <td data-bbox="332 829 865 968">3. Jobs produced with high accuracy and close tolerance.</td> <td data-bbox="865 829 1395 968">3. Care need to be taken to produce jobs with high accuracy and close tolerance.</td> </tr> <tr> <td data-bbox="332 968 865 1106">4. Blanking, piercing or punching operations are performed.</td> <td data-bbox="865 968 1395 1106">4. Blanking, drawing, bending operations performed.</td> </tr> <tr> <td data-bbox="332 1106 865 1171">5. e.g. washer</td> <td data-bbox="865 1106 1395 1171">5. e.g. drawing cup shaped part.</td> </tr> </tbody> </table>	Compound die	Combination die	1. Any two cutting operations can be performed at one station.	1. Both cutting and forming operations can be performed at one station.	2. Both operations performed in a single stroke of press	2. Two separate strokes of press.	3. Jobs produced with high accuracy and close tolerance.	3. Care need to be taken to produce jobs with high accuracy and close tolerance.	4. Blanking, piercing or punching operations are performed.	4. Blanking, drawing, bending operations performed.	5. e.g. washer	5. e.g. drawing cup shaped part.	<b>04</b>
Compound die	Combination die														
1. Any two cutting operations can be performed at one station.	1. Both cutting and forming operations can be performed at one station.														
2. Both operations performed in a single stroke of press	2. Two separate strokes of press.														
3. Jobs produced with high accuracy and close tolerance.	3. Care need to be taken to produce jobs with high accuracy and close tolerance.														
4. Blanking, piercing or punching operations are performed.	4. Blanking, drawing, bending operations performed.														
5. e.g. washer	5. e.g. drawing cup shaped part.														
2	f)	<b>Draw and identify parts of standard die set.</b>	<b>04</b>												
	Ans:	<p>Answer: (Sketch :-2 marks, labelling -2marks)</p> 	<b>04</b>												
3		<b>Attempt any FOUR of the following:</b>	<b>16</b>												
	a)	<b>State “Plane washer” making process with use of combination die.</b>	<b>04</b>												
	Ans:	(Explanation 02 Marks Figure 02 Mark) (Note: The plain washers can be produced by using Compound die or Progressive													

die. It is not possible to use combination die for making plain washers, so consider compound die or progressive die for answer. However credit should be given to any other suitable answer using combination die.)

**Compound Die:**

Figure shows a simple compound die in which a washer is made by one stroke of the press. The washer is produced by blanking and piercing operations. Simultaneous blanking and piercing is achieved by providing blanking and piercing element in both the member of die, i.e. the upper and the lower member of the die. These elements are set exactly opposite to each other so that piercing punch acts in the opposite direction with respect to the blanking punch. In this way blanking and piercing Operations are performed simultaneously. The flatness of the blank is achieved during cutting operation by knock out plate.



**Compound Die**

OR

**Progressive die for making plain washer**

In a progressive die two or more operations are performed simultaneously at two or more stations with each press stroke by mounting separate sets of dies and punch. The metal is progressed from one station to other. Figure shows progressive punching and blanking die .The sheet metal is fed into the first die where a hole is pierced by piercing die set in first cutting stroke of ram. The plate is then advanced in next station. In the second stroke of ram the pilot enters into the pierced hole and correctly locate it while the blanking punch descend and shear the plate to form a washer.




**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403



1. Stop 2.sheet metal 3.pilot 4.blanking punch 5.ram 6.piercing punch 7.stripper 8.die

3	b)	<p><b>State the working principle of gas welding.</b></p>	04
		<p>Working principle of gas welding: (Explanation 02 Marks, Fig 02Mark)</p> <p>Gas Welding is a fusion welding process. It joins metals, using the heat of combustion of the oxygen/air and combustible gas (i.e. acetylene, hydrogen, propane, or butane) mixture. The purpose of flame is to heat and melt the parent metal and filler rod of the joint. The intense heat produced melts the edges of parts and fuses together to form the welded, generally with the addition of a filler metal. The torch mixes a combustible gas with oxygen in the proper ratio and flow rate providing combustion process at a required temperature. The flame temperature is determined by a type of the combustible gas and proportion of oxygen in the combustion mixture: 4500°F - 6300°F (2500°C - 3500°C). Depending on the proportion of the fuel gas and oxygen in the combustion mixture, the flame may be chemically neutral (content of the gases), oxidizing (excess of oxygen), and carburizing (excess of fuel gas). Welding does not require the components to be forced together under pressure until the weld is forms and solidifies.</p> <p style="text-align: center;">Fig. Gas Welding</p>	02




3	c)	<b>Differentiate between TIG and MIG.</b>	<b>04</b>																											
	<b>Ans:</b>	(Each point 1 Mark i.e. 1x4 = 4 Marks) <table border="1"><thead><tr><th>Sr. No</th><th>TIG</th><th>MIG</th></tr></thead><tbody><tr><td>1</td><td>In Tungsten Inert Gas arc welding, non- consumable tungsten electrode is used</td><td>In Metal Inert Gas arc welding, consumable metallic electrode is used</td></tr><tr><td>2</td><td>Both AC and DC supply may be used</td><td>DC with reverse polarity is used</td></tr><tr><td>3</td><td>Filler metal may or may not be used</td><td>Filler metal not used as electrode itself serve both purposes of producing arc and filler metal</td></tr><tr><td>4</td><td>Not used for welding plates thicker than 6 mm</td><td>Best suited for welding jobs thicker than 6 mm</td></tr><tr><td>5</td><td>Welding speed is low</td><td>Welding speed is fast</td></tr><tr><td>6</td><td>Electrode feed not required</td><td>Electrode need to be feed at constant speed from wire reel</td></tr><tr><td>7</td><td>Penetration not so much deeper</td><td>Deeper penetration is obtained</td></tr><tr><td>8</td><td>Requires skilled operator</td><td>Less skilled operator can do the job</td></tr></tbody></table>	Sr. No	TIG	MIG	1	In Tungsten Inert Gas arc welding, non- consumable tungsten electrode is used	In Metal Inert Gas arc welding, consumable metallic electrode is used	2	Both AC and DC supply may be used	DC with reverse polarity is used	3	Filler metal may or may not be used	Filler metal not used as electrode itself serve both purposes of producing arc and filler metal	4	Not used for welding plates thicker than 6 mm	Best suited for welding jobs thicker than 6 mm	5	Welding speed is low	Welding speed is fast	6	Electrode feed not required	Electrode need to be feed at constant speed from wire reel	7	Penetration not so much deeper	Deeper penetration is obtained	8	Requires skilled operator	Less skilled operator can do the job	<b>04</b>
Sr. No	TIG	MIG																												
1	In Tungsten Inert Gas arc welding, non- consumable tungsten electrode is used	In Metal Inert Gas arc welding, consumable metallic electrode is used																												
2	Both AC and DC supply may be used	DC with reverse polarity is used																												
3	Filler metal may or may not be used	Filler metal not used as electrode itself serve both purposes of producing arc and filler metal																												
4	Not used for welding plates thicker than 6 mm	Best suited for welding jobs thicker than 6 mm																												
5	Welding speed is low	Welding speed is fast																												
6	Electrode feed not required	Electrode need to be feed at constant speed from wire reel																												
7	Penetration not so much deeper	Deeper penetration is obtained																												
8	Requires skilled operator	Less skilled operator can do the job																												
3	d)	<b>Explain the resistance Welding</b>	<b>04</b>																											
	<b>Ans:</b>	Resistance Welding: (Explanation 02 Marks, Fig 02Mark) Resistance welding is a group of welding processes wherein coalescence is produced by the heat obtained from resistance of the work to the flow of electric current in a circuit of which the work is a part and by the application of pressure. No filler material is needed. Resistance welding is employed to join overlapping strips, sheets or plates of metal at small areas .The pieces are assembled between two electrodes, which must possess high electrical and thermal conductivity and retain the required strength at high temperatures, so they are made of pure copper for a limited amount of service, and of alloys of copper or tungsten, or copper and chromium for continuous working. When current is turned on, the pieces are heated at their contacts to a welding temperature, and with the aid of mechanical pressure the electrodes are forced against the metal to be welded.	<b>02</b>																											

**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403



3	e)	<b>Compare resistance welding and arc welding.</b>	<b>04</b>																											
	Ans:	<p><b>(Each point 1 M i.e. 1x4 = 4 M)</b></p> <table border="1"> <thead> <tr> <th data-bbox="332 976 446 1018">Sr. No</th> <th data-bbox="446 976 917 1018">Resistance Welding</th> <th data-bbox="917 976 1380 1018">Arc Welding</th> </tr> </thead> <tbody> <tr> <td data-bbox="332 1018 446 1060">1</td> <td data-bbox="446 1018 917 1060">It is plastic welding</td> <td data-bbox="917 1018 1380 1060">It is fusion welding.</td> </tr> <tr> <td data-bbox="332 1060 446 1239">2</td> <td data-bbox="446 1060 917 1239">Arc is produced by heat due to resistance of flow of current by work and by application of pressure</td> <td data-bbox="917 1060 1380 1239">Arc is produced by heating with an electric arc, mostly without application of pressure and filler material</td> </tr> <tr> <td data-bbox="332 1239 446 1281">3</td> <td data-bbox="446 1239 917 1281">Filler metal is not used</td> <td data-bbox="917 1239 1380 1281">Filler metal may used</td> </tr> <tr> <td data-bbox="332 1281 446 1354">4</td> <td data-bbox="446 1281 917 1354">High pressure welding can be achieved</td> <td data-bbox="917 1281 1380 1354">Low welding speed</td> </tr> <tr> <td data-bbox="332 1354 446 1396">5</td> <td data-bbox="446 1354 917 1396">Supply is A. C. only</td> <td data-bbox="917 1354 1380 1396">Supply may be A.C. or D.C.</td> </tr> <tr> <td data-bbox="332 1396 446 1438">6</td> <td data-bbox="446 1396 917 1438">Voltage required is low</td> <td data-bbox="917 1396 1380 1438">Striking voltage is high</td> </tr> <tr> <td data-bbox="332 1438 446 1501">7</td> <td data-bbox="446 1438 917 1501">Both similar and dissimilar metal can be welded easily.</td> <td data-bbox="917 1438 1380 1501">Welding of similar and dissimilar metal is quite difficult</td> </tr> <tr> <td data-bbox="332 1501 446 1575">8</td> <td data-bbox="446 1501 917 1575">Less skilled operator can do the job.</td> <td data-bbox="917 1501 1380 1575">More skilled operator is required to the job</td> </tr> </tbody> </table>	Sr. No	Resistance Welding	Arc Welding	1	It is plastic welding	It is fusion welding.	2	Arc is produced by heat due to resistance of flow of current by work and by application of pressure	Arc is produced by heating with an electric arc, mostly without application of pressure and filler material	3	Filler metal is not used	Filler metal may used	4	High pressure welding can be achieved	Low welding speed	5	Supply is A. C. only	Supply may be A.C. or D.C.	6	Voltage required is low	Striking voltage is high	7	Both similar and dissimilar metal can be welded easily.	Welding of similar and dissimilar metal is quite difficult	8	Less skilled operator can do the job.	More skilled operator is required to the job	<b>04</b>
Sr. No	Resistance Welding	Arc Welding																												
1	It is plastic welding	It is fusion welding.																												
2	Arc is produced by heat due to resistance of flow of current by work and by application of pressure	Arc is produced by heating with an electric arc, mostly without application of pressure and filler material																												
3	Filler metal is not used	Filler metal may used																												
4	High pressure welding can be achieved	Low welding speed																												
5	Supply is A. C. only	Supply may be A.C. or D.C.																												
6	Voltage required is low	Striking voltage is high																												
7	Both similar and dissimilar metal can be welded easily.	Welding of similar and dissimilar metal is quite difficult																												
8	Less skilled operator can do the job.	More skilled operator is required to the job																												
3	f)	<b>Explain the working of simple dies with neat sketch.</b>	<b>04</b>																											
	Ans:	<p>Simple Die: (Explanation 02 Marks, Fig 02Mark)</p> <p>Simple die or single action dies perform single operation for each stroke of the press slide. The operation may be cutting or forming operation such as blanking, punching, piercing etc. performed on these dies. The operations can be performed in a single action of the press slide giving output. These dies are simple in construction and can manufacture by conventional machining processes.</p>	<b>02</b>																											





**MODEL ANSWER**

WINTER- 17 EXAMINATION


Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

		 <p style="text-align: center;">OR</p> 	<b>02</b>
--	--	--	-----------

<b>4</b>		<b>Attempt any four of the following</b>	<b>16</b>
----------	--	--	-----------

4	a)	<b>Sketch and label different types of gas welding flames. Also give application of any one flame.</b>	
---	----	--	--

		<p>(Sketches of 3 Types- 3 marks, applications of any one -1 marks)</p> <p>1) Neutral Flame: - A neutral flame is obtained when equal amounts of oxygen and acetylene are mixed and burnt in a torch.</p>  <p>Applications: - stainless steel, cast iron, copper ,mild steel and aluminum</p>	<b>01</b>
--	--	---	-----------





**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

		<p>2) Oxidizing Flame: - If more oxygen is added, the cone becomes darker and more pointed, while the envelope becomes shorter and is called Oxidizing flame</p>  <p>Applications: - copper base alloy, zinc base metal, Brass and Bronze</p> <p>3) Carburizing Flame: A carburizing or reducing flame is obtained when acetylene is supplied more than oxygen.</p>  <p>Applications:-high carbon steel, nonferrous alloy</p>	<p>01</p> <p>01</p> <p>(01 mark for Application of any one)</p>
4	b)	<b>Explain electroplating process</b>	04
	Ans:	<p>Electroplating Process: (Explanation 02 Marks, Fig 02Mark)</p> <p>Electroplating may be described as a process of covering a surface or object usually metallic with a thin adherent coating of same or other metal by electrolysis. The form of original parts is retained. Figure shows a typical electroplating process.</p> <p>A DC voltage is applied between parts to be plated (which is made cathode) and anode material that is either material to be plated or an inert electrode. Both of these metals are immersed in a electrolyte, which may also contain dissolved salts of the metal to be plated, as well as additions to increase or control conductivity. When voltage is applied, metal ions migrate to the cathode lose their charge, and deposit on the surface. The main factors governing the plating are current density, concentration of electrolyte, and temperature of bath. Almost all commercially available metals can be plated, including aluminium, copper, brass, steel, zinc-based die castings. Plastics can be electroplated provided that they are first coated with an electrically conductive material. The most common plantings are zinc, chromium, nickel, copper, tin, and precious metals like gold platinum, silver and rhodium. Chromium plating is widely used because of its pleasing appearance and its resistance to corrosion and wear. Gold, silver and platinum plating are used in jewellery and electronic industry.</p>	02






**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403




02

4 c) Describe buffing process and enlist its any two applications. 04

**Ans:** Buffing process :- (Explanation 02 Marks, Fig 02Mark)  
Buffing is used to give a much higher, lustrous, reflective finish that cannot be obtained by polishing. The buffing process consists in applying very fine abrasives with rotating wheel. Buffing wheels are made of discs of linen, cotton, broad cloth and canvass. They are made more or less firm by the amount of stitching used to fasten the layers of the cloth together. The abrasive is mixed with binder and is applied either on the buffing wheel or on the work. The abrasives may consist of iron oxide chromium oxide, emery etc. The binder is a paste consisting of wax mixed with grease, paraffin and kerosene, or turpentine and other liquid.  
In this process, work piece is brought in contact with a revolving, cloth buffing wheel that has been charged with very fine abrasive. The abrasives removes minute amount of metal from the work piece, eliminate fine scratch marks and produce a very smooth surface. Buffing is used to apply high luster to the work piece.  
Applications: - Automobiles, motor-cycles, boats, bicycles, sporting items, tools, store fixtures, commercial and residential hardware and household utensils and appliances.

02








**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403




01

2. Absolute Co- ordinate system: (Explanation – 01 mark & Sketch– 01mark)

In Cartesian co–ordinate geometry system using incremental measurement. Each point is always specified using the path differential from the preceding point position. So in such a programming, controller must store and process additional path measurement, as shown in fig. It is a system in which the reference point to the next instruction is the end point of the preceding operation. Each data of applied to the system as a distance increment, measured from preceding point.

01



4

f) Give classification of CNC machines.

04

Ans: Classification of CNC machines. (Brief classification 4 marks)

A. According to control loop feedback system:

- 1) Open – loop system
- 2) Closed – loop system

B. According to type of tool motion control system:

- 1) Finite positioning control system:
  - a) Point – to – point system
  - b) Straight cut system
- 2) Continuous path system:
  - a) Two axes contouring
  - b) Two & half axes contouring



**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

		<p>c) Three axes contouring d) Multi – axis contouring C. According to programming methods: 1) Absolute programming method 2) Incremental programming method D. According to type of controller: 1) NC based controller system 2) CNC based controller system E. According to Operation of Machine 1) Swiss-style lathe / Swiss turning center 2) Combination lathe / 3-in-1 machine 3) Mini-lathe and micro-lathe 4) Wheel lathe</p>	04
5		<b>Attempt any FOUR of the following: (4 x 4)</b>	16
5	(a)	<b>With the help of block diagram explain closed loop control CNC system.</b>	04
	Ans:	<p>(02 Marks for Block Diagram And 02 Marks For Explanation.)</p> <p style="text-align: center;"><i>Figure : Block Diagram of Closed Loop Control System</i></p> <p>Special motors called servos are used for executing machine movements in closed loop system. The name indicates that the closed loop control system has a loop that is closed as shown in fig. A feedback device is used for this purpose. This makes the design of closed loop a little complicated and expensive. But a very high degree of accuracy is achieved in the movement of slide. This system is similar to open loop control system. But it consists of two additional devices in the form of feedback transducer and a comparator as shown in Fig. The transducer feedbacks the actual slide displacement to the comparator. The comparator compares the actually achieved slide movement with command signal. If there is any error then it is feedback to the MCU. The MCU then sends the corrective commands to the drive unit and the cycle repeats until there is no error signal from the comparator.</p>	<p>02 Marks for Block Diagram</p> <p>And 02 Marks For Explan ation.</p>



**MODEL ANSWER**

**WINTER- 17 EXAMINATION**

**Subject Title: Automobile Manufacturing Processes**

**Subject Code: 17403**

<b>5</b>	<b>(b)</b>	<p><b>Differentiate between conventional machine and CNC machine.</b></p> <p><i>(Any Four Points 01 mark each)</i></p> <p>Difference between Conventional Machine and CNC Machine:</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">S.N.</th> <th style="width: 45%;">Conventional Machine</th> <th style="width: 50%;">CNC Machine</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>Lead screw is used for axis movement.</td> <td>Ball screw is used for axis movement.</td> </tr> <tr> <td>2</td> <td>All operations are performed manually. (Except some auto mode).</td> <td>All operations are performed auto mode in single setting inside the machines.</td> </tr> <tr> <td>3</td> <td>There is no use of Servo motors &amp; stepping motors for slide movement</td> <td>Servo motors &amp; stepping motors are used for slide movement.</td> </tr> <tr> <td>4</td> <td>No Display units are provided in conventional m/c.</td> <td>Display units are provided in CNC m/c.</td> </tr> <tr> <td>5</td> <td>Less Accurate.</td> <td>More accurate.</td> </tr> <tr> <td>6</td> <td>More error due to operator.</td> <td>Less error due to operator.</td> </tr> <tr> <td>7</td> <td>Less Guarding arrangements.</td> <td>More guarding arrangements.</td> </tr> <tr> <td>8</td> <td>Small changes are not possible with conventional machines.</td> <td>Small changes are possible with CNC machines.</td> </tr> <tr> <td>9</td> <td>No dry run facility.</td> <td>Dry run facility.</td> </tr> <tr> <td>10</td> <td>Cycle time calculations, nos. of jobs produced, total run time, idle time cannot be obtained.</td> <td>Cycle time calculations, nos. of jobs produced, total run time, idle time can be obtained.</td> </tr> <tr> <td>11</td> <td>It does not compensate tool wear.</td> <td>It compensates tool wear.</td> </tr> <tr> <td>12</td> <td>No simulation.</td> <td>Simulation.</td> </tr> </tbody> </table>	S.N.	Conventional Machine	CNC Machine	1	Lead screw is used for axis movement.	Ball screw is used for axis movement.	2	All operations are performed manually. (Except some auto mode).	All operations are performed auto mode in single setting inside the machines.	3	There is no use of Servo motors & stepping motors for slide movement	Servo motors & stepping motors are used for slide movement.	4	No Display units are provided in conventional m/c.	Display units are provided in CNC m/c.	5	Less Accurate.	More accurate.	6	More error due to operator.	Less error due to operator.	7	Less Guarding arrangements.	More guarding arrangements.	8	Small changes are not possible with conventional machines.	Small changes are possible with CNC machines.	9	No dry run facility.	Dry run facility.	10	Cycle time calculations, nos. of jobs produced, total run time, idle time cannot be obtained.	Cycle time calculations, nos. of jobs produced, total run time, idle time can be obtained.	11	It does not compensate tool wear.	It compensates tool wear.	12	No simulation.	Simulation.	<b>04</b>
S.N.	Conventional Machine	CNC Machine																																								
1	Lead screw is used for axis movement.	Ball screw is used for axis movement.																																								
2	All operations are performed manually. (Except some auto mode).	All operations are performed auto mode in single setting inside the machines.																																								
3	There is no use of Servo motors & stepping motors for slide movement	Servo motors & stepping motors are used for slide movement.																																								
4	No Display units are provided in conventional m/c.	Display units are provided in CNC m/c.																																								
5	Less Accurate.	More accurate.																																								
6	More error due to operator.	Less error due to operator.																																								
7	Less Guarding arrangements.	More guarding arrangements.																																								
8	Small changes are not possible with conventional machines.	Small changes are possible with CNC machines.																																								
9	No dry run facility.	Dry run facility.																																								
10	Cycle time calculations, nos. of jobs produced, total run time, idle time cannot be obtained.	Cycle time calculations, nos. of jobs produced, total run time, idle time can be obtained.																																								
11	It does not compensate tool wear.	It compensates tool wear.																																								
12	No simulation.	Simulation.																																								
	<b>Ans:</b>		<b>01 Mark each Any Four Points</b>																																							
<b>5</b>	<b>(c)</b>	<p><b>Give classification of tools used on turning centre.</b></p> <p><i>(Correct Answer = 04 marks)</i></p> <p>Classification of tools used on turning centre:</p> <p>A. On the Basis of Cutting Tool Construction</p> <p>(a) Solid tools.</p> <p>(b) Brazed tools.</p> <p>(c) Inserted bit tools.</p> <p>B. On the Basis of Cutting Tool Material</p> <p>(a) High speed steel (HSS).</p> <p>(b) High carbon tool steel (HCS).</p> <p>(c) Cast alloy.</p> <p>(d) Cemented carbide.</p> <p>(e) Ceramics.</p> <p>(f) Boron Nitride.</p> <p>(g) Diamond.</p>	<b>04</b>																																							
	<b>Ans:</b>		<b>04 Marks For Correct Answer</b>																																							
<b>5</b>	<b>(d)</b>	<p><b>State the procedure for developing the part program.</b></p> <p><i>(Any one method four marks)</i></p> <p>Procedure for developing part program</p>	<b>04</b>																																							
	<b>Ans:</b>																																									



		<p>There are two methods of part programming:-</p> <p><b>A) Manual Part Programming:</b></p> <p>To prepare a part program using the manual method</p> <ol style="list-style-type: none"><li>1) The programmer writes the machining instructions on a special form called a part programming manuscript. The manuscript is a listing of the relative tool and work piece location.</li><li>2) The NC tape is prepared directly from the manuscript.</li><li>3) Define the axis coordinates in relation to the work part.</li><li>4) Define safe (target point) point &amp; origin point (work zero)</li><li>5) The tape is inserted to read the first block in to the system.</li><li>6) The function like machining, tool changing, spindle ON/OFF ,coolant ON/OFF, program stop and tape rewinding are carried out as per the program.</li></ol> <p style="text-align: center;"><b>OR</b></p> <p><b>B) Computer –Assisted Part Programming (CAPP): -</b></p> <p>This method is useful for most critical and complex parts. The part programmer and the computer are the main tool in this method.</p> <ol style="list-style-type: none"><li>1) The part programmer first defines the work part geometry.</li><li>2) He specifies the operation sequence and tool path.</li><li>3)The computer interprets the list of part programming instructions, performs the necessary calculations to convert this into a detailed set of machine tool motion commands, and then controls a tape device to prepare the tape.</li><li>4) The tape is verified for accuracy.</li><li>5)The NC system machine makes the part according to the instructions on tape</li></ol>	<p style="text-align: center;"><b>04 Marks For Any One method</b></p>
<b>5</b>	<b>(e)</b>	<b>State the function of ‘G’ Codes and ‘M’ codes with any two examples.</b>	<b>04</b>
	<b>Ans:</b>	<p><i>(02 Marks For Functions And 02 Marks For Its Example)</i></p> <p><b>‘G’ Codes ( Preparatory Functions)</b></p> <p>The preparatory function instructs the machine tool to get prepared for the operation to follow, the preparatory function is represented by two digits preceded by letter ‘G’ e.g. G02, G04, G97, G96, etc.</p> <ol style="list-style-type: none"><li>(i) G00 – Rapid Positioning,</li><li>(ii) G01- Linear Interpolation ,</li><li>(iii)G90 – Absolute Programming etc.</li></ol> <p><b>M- codes (Miscellaneous function)</b></p> <p>The Miscellaneous function word is used to specify certain Miscellaneous function or auxiliary functions which do not relate to the dimensional movements of the machine.</p> <p>The Miscellaneous function is represented by two digits preceded by letter ‘M’</p>	<p style="text-align: center;"><b>02 Marks For Function s And 02 Marks For Its Example</b></p>



**MODEL ANSWER**

**WINTER- 17 EXAMINATION**

**Subject Title: Automobile Manufacturing Processes**

**Subject Code: 17403**

		<p>e.g. M00, M05, M08, M30 etc. i) M02 - Program end ii) M06 - Tool change iii) M08 – Coolant ON</p>																												
<b>5</b>	<b>(f)</b>	<b>Differentiate between lapping and honing process.</b>	<b>04</b>																											
	<b>Ans:</b>	<p><i>(01 Marks For Each Points )</i></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 5%;">S. N.</th> <th style="width: 45%;">Lapping</th> <th style="width: 45%;">Honing</th> </tr> </thead> <tbody> <tr> <td style="text-align: center;">1</td> <td>Lapping is a finishing process in which tool used is called lap.</td> <td>Honing is a finishing process in which tool used is called hone.</td> </tr> <tr> <td style="text-align: center;">2</td> <td>The lapping process involves passing a part between one or two large flat-lap plates or wheels.</td> <td>Tool has combined reciprocating and rotary motion of tool.</td> </tr> <tr> <td style="text-align: center;">3</td> <td>Cutting action takes place by fluid that contains an abrasive.</td> <td>Cutting action takes place by abrasive sticks.</td> </tr> <tr> <td style="text-align: center;">4</td> <td>The Process is used to corrects minor imperfections of shape, refines surface finish (mirrors finishes are common)</td> <td>The process is used to remove tool marks of previous operations.</td> </tr> <tr> <td></td> <td>Used for flat and slightly spherical</td> <td>Used for round holes</td> </tr> <tr> <td style="text-align: center;">5</td> <td>Applications: Precision Plug Gauges, Metallic Bearing Surfaces, Optical Lenses, etc.</td> <td>Applications: Cylinders of an IC engine, air bearing spindles, gears etc.</td> </tr> <tr> <td style="text-align: center;">6</td> <td>Used to achieve super-flat surfaces and incredibly tight tolerances on parts that require accuracy at the microscopic level.</td> <td>Used to improve certain form characteristics such as cylindricity, surface finish, or sphericity.</td> </tr> <tr> <td style="text-align: center;">7</td> <td>Lapping removes much less material than honing</td> <td>Honing removes more material than Lapping</td> </tr> </tbody> </table>	S. N.	Lapping	Honing	1	Lapping is a finishing process in which tool used is called lap.	Honing is a finishing process in which tool used is called hone.	2	The lapping process involves passing a part between one or two large flat-lap plates or wheels.	Tool has combined reciprocating and rotary motion of tool.	3	Cutting action takes place by fluid that contains an abrasive.	Cutting action takes place by abrasive sticks.	4	The Process is used to corrects minor imperfections of shape, refines surface finish (mirrors finishes are common)	The process is used to remove tool marks of previous operations.		Used for flat and slightly spherical	Used for round holes	5	Applications: Precision Plug Gauges, Metallic Bearing Surfaces, Optical Lenses, etc.	Applications: Cylinders of an IC engine, air bearing spindles, gears etc.	6	Used to achieve super-flat surfaces and incredibly tight tolerances on parts that require accuracy at the microscopic level.	Used to improve certain form characteristics such as cylindricity, surface finish, or sphericity.	7	Lapping removes much less material than honing	Honing removes more material than Lapping	<b>01 Marks For Each Points</b>
S. N.	Lapping	Honing																												
1	Lapping is a finishing process in which tool used is called lap.	Honing is a finishing process in which tool used is called hone.																												
2	The lapping process involves passing a part between one or two large flat-lap plates or wheels.	Tool has combined reciprocating and rotary motion of tool.																												
3	Cutting action takes place by fluid that contains an abrasive.	Cutting action takes place by abrasive sticks.																												
4	The Process is used to corrects minor imperfections of shape, refines surface finish (mirrors finishes are common)	The process is used to remove tool marks of previous operations.																												
	Used for flat and slightly spherical	Used for round holes																												
5	Applications: Precision Plug Gauges, Metallic Bearing Surfaces, Optical Lenses, etc.	Applications: Cylinders of an IC engine, air bearing spindles, gears etc.																												
6	Used to achieve super-flat surfaces and incredibly tight tolerances on parts that require accuracy at the microscopic level.	Used to improve certain form characteristics such as cylindricity, surface finish, or sphericity.																												
7	Lapping removes much less material than honing	Honing removes more material than Lapping																												
<b>6</b>		<b>Attempt any TWO of the following: (2 x 8)</b>	<b>16</b>																											
<b>6</b>	<b>(a)</b>	<b>Prepare a part program for following component. Also give co-ordinate system. Assume suitable data if required. Refer Fig. No. 1.</b>	<b>08</b>																											



**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

Ans: (02 Mark for Coordinate System with figure and 06 Marks for Correct Program )




Fig. No. 1

Point	X-Coordinate	Z-Coordinate
P0	0.0	2.0
P1	0.0	0.0
P2	22.0	0.0
P3	30.0	-35.0
P4	30.0	-65.0
P5	36.0	-68.0
P6	36.0	-103.0
P7	50.0	-103.0
P8	50.0	-113.0
P9	60.0	-113.0

Assumptions (may differ for every student)

Spindle Speed=1000RPM, Feed Rate=0.2 mm/rev. Carbide Insert Used DNMG 150404, Tool Holder Used PDLNL 2525 M15

PROGRAM:

O1234;

```

N001 G28 U0.0 W0.0;
N002 G90 G97 G98 G21;
N003 M06 T0101 M08;
N004 M04 S1000;
N005 G00 X0.0 Z2.0;
N006 G01 X22.0 Z0.0 F0.2;
N007 G01 X30.0 Z-35.0;
N008 G01 X30.0 Z-65.0;
N009 G03 X36.0 Z-68.0 R3.0;
N010 G01 X36.0 Z-103.0;
N011 G01 X50.0 Z-103.0;
N012 G01 X50.0 Z-113.0;
N013 G01 X60.0 Z-113.0;
N014 M05 M09;
N015 G28 U0.0 W0.0;
N016 M30;

```

02  
Mark  
For  
Coordinate  
System  
And

06  
Marks  
For  
Correct  
Program

6 (b) Prepare a part program for following component (refer Fig. No. 2). Assume suitable data if required. Assume plate thickness is 50 mm.

08





**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

**Ans:** (02 Mark For Coordinate System with figure and 06 Marks For Correct Program)  
[NOTE :Program written for drilling operation only can be considered for full marks]




Fig. No 2

Assumptions: (may differ for every student)

Tool No.1: Solid Carbide End Mill of 25 mm Diameter X 60 mm Flute Length X 110 mm Overall Length is used.

Tool No 2: Solid Carbide Drill 10 mm X 65 mm X 110 mm is used.

PROGRAM;

O1234; (Side Milling of Plate 50X 80 X 50 mm Thick)

```

N001 G28 X0.0 Y0.0 Z0.0;
N002 G90 G99 G97 G42 G21;
N003 M06 T0101 M08;
N004 M03 S750;
N005 G00 X-10.0 Y-10.0 Z0.0;
N006 G01 X0.0 Y0.0 Z-55.0 F150.0;
N007 G01 X80.0 Y0.0;
N008 G01 X80.0 Y50.0;
N009 G01 X0.0 Y50.0;
N010 G01 X0.0 Y0.0;
N011 G01 X -10.0 Y-10.0 Z0.0;
N012 M05 M09;
N013 G40;
N014 G28X0.0 Y0.0 Z0.0;
N015 M06 T0202 M08; (Drilling of Diameter 10 mm holes X 3Nos.)
N016 M03 S500;
N017 G00 X10.0 Y10.0 Z2.0;
N018 G01 Z-55.0 F50.0;
N019 G01 Z2.0;
N020 G00 X10.0 Y40.0;
N021 G01 Z-55.0;
N022 G01 Z2.0;
N023 G00 X70.0 Y40.0;

```

02  
Mark  
For  
Coordin  
ate  
System  
And

06  
Marks  
For  
Correct  
Program



**MODEL ANSWER**

WINTER- 17 EXAMINATION

Subject Title: Automobile Manufacturing Processes

Subject Code: 17403

		N024 G01 Z-55.0; N025 G01 Z2.0; N026 G28 X0.0 Y0.0 Z0.0; N027 M05 M09; N028 M30;	
6	(c)	<b>Describe with neat sketch working of progressive die. Also write functions of any four parts of progressive die.</b>	08
	Ans:	<p>(02 Marks For Sketch, 02 Marks For Description, 01 Mark For Function Of Each Part)</p> <p>Figure: Progressive Die</p> <p>In a progressive die two or more operations are performed simultaneously at two or more stations with each press stroke by mounting separate sets of dies and punch. The metal is progressed from one station to other. Figure shows progressive punching and blanking die. The sheet metal is fed into the first die where a hole is pierced by piercing die set in first cutting stroke of ram. The plate is then advanced in next station. In the second stroke of ram the pilot enters into the pierced hole and correctly locate it while the blanking punch descend and shear the plate to form a washer</p> <p>Functions :</p> <p>(1) Bolster Plate: It is part of press machine attached to the bed, which supports and hold the die block at required position.</p> <p>(2) Die: It is a female part of a complete tool, used for producing work in press.</p> <p>(3) Punch: It is a male part of die assembly, use to insert into the die for producing work in press</p> <p>(a) Piercing Punch: The sheet metal is fed into the first die where a hole is pierced by piercing punch</p>	<p>02 Marks For Sketch,</p> <p>02 Marks For Description,</p> <p>01 Mark For Function Of Each Part.</p>



**MODEL ANSWER**

**WINTER- 17 EXAMINATION**

**Subject Title: Automobile Manufacturing Processes**

**Subject Code: 17403**

	<p>in first cutting stroke of ram.</p> <p>(b) Blanking Punch: In the second stroke of ram the pilot of blanking punch enters into the pierced hole and shear the plate to form a washer</p> <p>(4) Guide Pin (Pilot): To locate the blanking punch correctly, while the blanking punch descend.</p> <p>(5) Punch Holder: To hold the punch/s in proper position.</p> <p>(6) Stripper Plate: It is used to strip the metal strip from the punch or die. It also guides the t metal sheet</p>	
--	---	--