

Subject Code: 17511

**Model Answer** 

Page 1 of 26


### Important suggestions to examiners:

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more importance. (Not applicable for subject English and communication skills)
- 4) While assessing figures, examiner may give credit for principle components indicated in a figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case some questions credit may be given by judgment on part of examiner of relevant answer based on candidate understands.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.

Q.1	Attempt any Five:         (4 x 5 = 20)	Marks)
<b>a</b> )		
Ans:	Working principle of 3 phase induction motor:(4)	Marks)
	The principle of working of 3 phase induction motor on the basis of t	he concept
	of rotating magnetic field can be explained as follows:	
	When 3-Ph AC supply is given to stator of three phase induction moto	<b>r</b> , rotating
	magnetic field is produced in air gap, which starts to rotate around the stator fra-	ame with
	synchronous speed (Ns = $120f/P$ ). There is a relative motion between rotating n	magnetic
	field and stationary rotor conductors which is (Ns-N). According to faradays la	aws of
	electromagnetic induction, emf will be induced in the rotor conductors. As the	rotor
	conductor are short circuited on either sides by end rings, current flows through	ough it. Due
	to interaction between stator and rotor flux rotor starts rotating .Rotor rotates in	n the same
	direction as that of rotating magnetic field.	
	According to 'Lenz Law' the rotor current should oppose the cause which	h produces
	it i.e. relative speed Ns-N. So the rotor will try to catch the rotating magnetic fi	ield speed
	Ns to minimize the relative speed.	
	But due to inertia and friction of rotor, they never succeed. Hence rotor v continuous rotation with speed N, which is always less than Ns.	vill be in



### Summer-2016 Examinations





			Summer-	2016 Examin	ations	
Subje	ct Code: 1	17511	Mo	<u>del Answer</u>		Page 3 of 26
	transf	former whose	e secondary is sho	rt circuited.)	Such a huge curren	nt is harmful to the
	motor	r. Therefore	there is necessity of	of starter for 3	3-phase induction	motor to control the
	startii	ng current.				
	ii) The n	ames of start	ers used for 3-phas	e induction m	notor.	(2 Mark)
		1) DOL St	arter			
		2) Star-De	lta Starter			
		3) Rotor re	esistance starter			
		4) Auto tra	nsformer Starter			
I)	List out alternat		tages of having	a stationary	armature and	rotating field of 3-ph
s:	arternat			(Any four	Point Expected e	ach point 1 Marks)
	Follow	ing Advanta	ages of stationary	armature a	nd rotating field	of a 3-phase
	alterna	itor:				
	Varie	ous advantag	ges of rotating field	d can be state	ed as,	
	1)	The generati	on level of a.c. vo	ltage may be	higher as 11 KV to	o 33 KV. This gets
		induced in th	ne armature. For st	ationary arm	ature large space c	can be provided to
		accommodat	te large number of	conductors a	and the insulations	
	2)	It is always b	better to protect his	gh voltage w	inding from the ce	ntrifugal forces caused
		due to the ro	tation. So high vo	ltage armatui	e is generally kept	t stationary. This
		avoids the in	teraction of mecha	anical and ele	ectrical stresses.	
	3)	It is easier to	collect larger cur	rents at very	high voltage from	a stationary member
		than from th	e slip ring and bru	sh assembly.	The voltage requ	ired to be supplied to
		the field is v	ery low (110 V to	220 V d.c.) a	and hence can be e	asily supplied with the
		help of slip 1	ring and brush asse	embly by kee	ping it rotating.	
	4)	Due to low w	oltage level on the	e field side, t	he insulation requi	red is less and hence
		field system	has very low inert	tia. It is alway	ys better to rotate l	ow inertia system than
		high inertia,	as efforts required	l to rotate lov	v inertia system are	e always less.
	5)	Rotating fiel	d makes the overa	ll constructio	on very simple. Wi	th simple, robust
		mechanical of	construction and lo	ow inertia of	rotor, it can be driv	ven at high speeds. So
		greater outpu	ut can obtain from	an alternator	of given size.	



Subje	Summer- 2016 Examinationsct Code: 17511Model Answer	Page 4 of 26
	<ul> <li>6) If field is rotating, to excite it be external d.c. supply two slip rings each for positive and negative terminals. As against this, in three p armature the minimum number of slip rings required are three and insulated due to high voltage levels.</li> <li>7) The ventilation arrangement for high voltage side can be improved stationary.</li> <li>8) Rotating field is comparatively light and can run with high speed. OR</li> <li>Following Advantages of stationary armature and rotating field of a 3 alternator:</li> <li>The field winding of an alternator is placed on the rotor and is supply through two slip rings. The 3-phase armature winding is place This arrangement has the following advantages:</li> <li>1. It is easier to insulate stationary armature winding for high voltages for which are usually designed. It is because they are not subjected to centrifu also extra space is available due to the stationary arrangement of the is easier to insulate stationary armature winding for high AC voltage have as high a value as 30KV or more.</li> <li>2. The stationary 3-phase armature can be directly connected to load v through large, unreliable slip rings and brushes.</li> <li>3. Only two slip rings are required for d.c. supply to the field winding Since the exciting current is small, the slip rings are transferred t low power DC field current which can, therefore be easily insulated 4. Due to simple and robust construction of the rotor, higher speed of the sum of the construction of the rotor.</li> </ul>	hase rotating can not be easily if it is kept <b>3-phase</b> connected to d.c. ced on the stator. the alternators gal forces and e armature. Or It e, which may without going on the rotor. uired are of light o the low voltage,
	is possible. This increases the output obtainable from a machine of	
<b>e</b> )	State the necessity conditions of parallel operation of 3-ph alternator.	
Ans:	<ul> <li>Conditions of parallel operation of 3-ph alternator:- <ul> <li>(Any Four Point expected)</li> </ul> </li> <li>1. The phase sequence of both 3-ph alternators must be same.</li> <li>2. The AC voltages of both 3-ph alternators should be equal.</li> </ul>	d: 1 Mark each)
	<ul> <li>3. The frequencies of both 3-ph alternators must be equal.</li> <li>4. Phase voltages of both 3-ph alternators must be in proper phase relation phase voltages of both 3-ph alternators must be identical.</li> </ul>	on or polarity of



**Model Answer** Subject Code: 17511 Page 5 of 26 Give the reason why single phase induction motors are not self starting. f) **Reason for single phase induction motors are not self starting:** Ans: (4 Mark) > When single phase AC supply is given to main winding it produces alternating flux. > According to double field revolving theory, alternating flux can be represented by two opposite rotating flux of half magnitude. > These oppositely rotating flux induce current in rotor & there interaction produces two opposite torque hence the net torque is Zero and the rotor remains standstill.  $\geq$ Hence Single-phase induction motor is not self starting. OR Single phase induction motor has distributed stator winding and a squirrelcage rotor. When fed from a single-phase supply, its stator winding produces a flux (or field) which is only alternating i.e. one which alternates along one space axis only. It is not a synchronously revolving (or rotating) flux as in the case of a two or a three phase stator winding fed from a 2 of 3 phase supply. Now, alternating or pulsating flux acting on a stationary squirrel-cage rotor cannot produce rotation (only a revolving flux can produce rotation). That is why a single phase motor is not self-starting. Give any two advantages and two disadvantages of single phase induction generator. **g**) Advantages of single phase induction generator: (Any Two expected : 1 Mark each) Ans: 1. They are robust and sturdy. 2. Are cheaper in cost. 3. The construction is simple. 4. Low Maintenance. Very little maintenance is required. 5. It does not require any complex circuit for starting. 6. They can be operated in hazardous environments and even under water as they do not produce sparks. Disadvantages of single phase induction generator: (Any Two expected : 1 Mark each) 1. Speed control is difficult 2. At low loads, the power factor drops to very low values **3.** Efficiency drops at low loads. This is because; the low power factor causes a higher

current to be drawn. This results in higher copper losses.



# Subject Code: 17511

Model Answer

Page 6 of 26

Q.2	Attempt any FOUR : 16 Marks				
a)	Derive the condition for maximum torque at running condition of a 3-ph induction motor.				
Ans:	Note: The student can follow for different method of derivation also				
	Let us consider the equation of torque,				
	$T = \frac{K \phi S E_2 R_2}{R_2^2 + S^2 X^2}$ (1 Mark)				
	Condition of maximum torque can be found out by taking derivative of torque				
	equation w.r.t. Slip and equating it to zero. For the simplicity of derivation, let us put $\frac{1}{T} = M$				
	$M = \frac{R_2^2 + S^2 X_2^2}{K \phi S E_2 R_2}$ (1 Mark)				
	$M = \frac{1}{K\phi S E_2 R_2} $ (1 Mark)				
	$\mathbf{P}^2$ $\mathbf{C}^2 \mathbf{V}^2$ (1 Mark)				
	$M = \frac{R_2^2}{K \phi S E_2 R_2} + \frac{S^2 X_2^2}{K \phi S E_2 R_2}$				
	$M = \frac{R_2}{K \phi S E_2} + \frac{S X^2}{K \phi E_2 R_2}$				
	$\frac{d(M)}{dS} = \frac{d}{dS} \left[ \frac{R_2}{K \phi S E_2} + \frac{S X_2^2}{K \phi E_2 R_2} \right] = 0$ (1 Mark)				
	$-\frac{R_2}{K\phi S^2 E_2} + \frac{X_2^2}{K\phi E_2 R_2} = 0$				
	$\frac{X_2^2}{K \phi E_2 R_2} = \frac{R_2}{K \phi S^2 E_2}$				
	$K \phi E_2 R_2  K \phi S^2 E_2$				
	$S^2 X_2^2 = R_2^2$				
	$\frac{S^2 X_2^2}{K \phi E_2 R_2} = \frac{R_2^2}{K \phi S^2 E_2}$				
	$S^2 X_2^2 = R_2^2$				
	$\therefore R_2 = S X_2$				
	$\ldots \mathbf{K}_2 = \mathbf{S} \mathbf{X}_2$				
	(1Mark)				
	This is the condition for maximum torque of 3-Ph induction motor under running				
<b>b</b> )	How speed of 3-ph induction motor is controlled by using pole changing method ?				
Ans:	by Following reason varying number of poles of the stator winding (pole changing				
	control): (4 Mark)				
	1. The synchronous speed of an induction motor is given by $N_s = \frac{120 \times f}{P}$ .				



2. It is clear from the equation that if the number of poles of the stator is decreased, the speed of the motor will increased.         3. When the number of poles are increases, the speed of the motor decreases.         4. The poles of the stator winding can be changed by having two or more separate stator windings of different pole combination housed in common stator frame. By selecting proper number of pole combination, Ns can be varied and hence the speed.         OR         From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for <u>squirrel cage induction motors</u> , as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1000 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1000 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1000 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM <td cols<="" th=""><th>Subje</th><th>ct Code: 17511</th><th>Summer– 2016 Examinations <u>Model Answer</u></th><th>Page 7 of 26</th></td>	<th>Subje</th> <th>ct Code: 17511</th> <th>Summer– 2016 Examinations <u>Model Answer</u></th> <th>Page 7 of 26</th>	Subje	ct Code: 17511	Summer– 2016 Examinations <u>Model Answer</u>	Page 7 of 26
<ul> <li>When the number of poles are increases, the speed of the motor decreases.</li> <li>The poles of the stator winding can be changed by having two or more separate stator windings of different pole combination housed in common stator frame. By selecting proper number of pole combination, Ns can be varied and hence the speed.</li> <li>OR</li> <li>From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for <u>squirrel cage induction motors</u>, as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles in stator poles in same slots.</li> <li>For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz</li> <li>i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) bistribution factor iv) Pitch factor.</li> <li>Ans:</li> <li>(Each Definition: 1 Mark)</li> <li>i) Leakage reactance:</li> <li>ii) bistribution factor iv) Pitch factor.</li> <li>Men armature carries a current, it produces its own flux. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux</li> <li>When armature carries a current, it produces its own flux. Some part of this flux com</li></ul>		2. It is clea	r from the equation that if the number of poles	of the stator is decreased,	
<ul> <li>4. The poles of the stator winding can be changed by having two or more separate stator windings of different pole combination housed in common stator frame. By selecting proper number of pole combination, Ns can be varied and hence the speed.</li> <li>OR</li> <li>From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for <u>squirrel cage induction motors</u>, as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles in same slots.</li> <li>For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz</li> <li>i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM</li> <li>i) Leakage reactance:</li> <li>The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux</li> <li>OR</li> <li>When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage</li> </ul>		the spee	d of the motor will increased.		
stator windings of different pole combination housed in common stator frame. By selecting proper number of pole combination, Ns can be varied and hence the speed.         OR         From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for <u>squirrel cage induction motors</u> , as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		3. When th	e number of poles are increases, the speed of the	he motor decreases.	
electing proper number of pole combination, Ns can be varied and hence the speed.         OR         From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for squirrel cage induction motors, as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		4. The pole	es of the stator winding can be changed by having	ing two or more separate	
OR         From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for <u>squirrel cage induction motors</u> , as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux.         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		stator w	indings of different pole combination housed in	n common stator frame. By	
OR         From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for squirrel cage induction motors, as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       I)         When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		selecting	g proper number of pole combination, Ns can b	e varied and hence the	
From the above equation of synchronous speed, it can be seen that synchronous speed (and hence, running speed) can be changed by changing the number of stator poles. This method is generally used for squirrel cage induction motors, as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		speed.			
speed (and hence, running speed) can be changed by changing the number of stator         poles. This method is generally used for squirrel cage induction motors, as squirrel         cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved         by two or more independent stator windings wound for different number of poles in         same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for         6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous         impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:         The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR         When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage			OR		
c)       poles. This method is generally used for squirrel cage induction motors, as squirrel cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz       i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM       ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		From th	e above equation of synchronous speed, it can	be seen that synchronous	
cage rotor adapts itself for any number of stator poles. Change in stator poles is achieved by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		speed (and her	nce, running speed) can be changed by changir	ng the number of stator	
by two or more independent stator windings wound for different number of poles in same slots.         For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		poles. This me	ethod is generally used for squirrel cage induc	c <b>tion motors,</b> as squirrel	
same slots.       For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		cage rotor ada	pts itself for any number of stator poles. Chang	ge in stator poles is achieved	
For example, a stator is wound with two 3phase windings, one for 4 poles and other for 6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		by two or mor	e independent stator windings wound for diffe	rent number of poles in	
6 poles. for supply frequency of 50 Hz         i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM         ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		same slots.			
<ul> <li>i) synchronous speed when 4 pole winding is connected, Ns = 120*50/4 = 1500 RPM</li> <li>ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM</li> <li>c) Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.</li> <li>Ans: (Each Definition: 1 Mark)</li> <li>i) Leakage reactance:</li> <li>The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux</li> <li>OR</li> <li>When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage</li> </ul>		For example,	a stator is wound with two 3phase windings, o	one for 4 poles and other for	
ii) synchronous speed when 6 pole winding is connected, Ns = 120*50/6 = 1000 RPM         c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		6 poles. for su	pply frequency of 50 Hz		
c)       Define each of the following term of alternator: i) Leakage reactance ii) Synchronous impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		i) synchronou	s speed when 4 pole winding is connected, Ns	= 120*50/4 = 1500 RPM	
c)       impedance iii) Distribution factor iv) Pitch factor.         Ans:       (Each Definition: 1 Mark)         i) Leakage reactance:       The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux         OR       When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		ii) synchronou	is speed when 6 pole winding is connected, Ns	= 120*50/6 = 1000 RPM	
<ul> <li>i) Leakage reactance:</li> <li>The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux</li> <li>OR</li> <li>When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called as ;leakage</li> </ul>	c)			reactance ii) Synchronous	
The working flux does not only passes through intended path. Some part of working flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux <b>OR</b> When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage	Ans:			(Each Definition: 1 Mark)	
flux will be lost due to leakage. Hence leakage reactance is defined as the factor or parameters which represents the leakage flux <b>OR</b> When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		i) Leakage reacta	nce:		
parameters which represents the leakage flux OR When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage					
<b>OR</b> When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		flux will be lost	due to leakage. Hence leakage reactance is de	fined as the factor or	
When armature carries a current, it produces its own flux. Some part of this flux completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage		parameters which	ch represents the leakage flux		
completes its path through the air around the conductors itself. Such a flux is called leakage flux. The equivalent reactance due to this leakage flux is called as ;leakage					
		completes its pa leakage flux. Th	ath through the air around the conductors itself.	Such a flux is called	



Subje	ect Code: 17511 Summer – 2016 Examinations Model Answer	Page 8 of 26
	ii) Synchronous impedance:	
	It is a fictitious impedance employed to account for the vo	ltage effects in armature
	circuit produced by the actual armature resistance, the actual arm	nature leakage reactance,
	and the change in air gap flux produced by armature reaction.	-
	OR	
	$\begin{split} Z_S &= R_a + j \; ( \; X_L + X_a \; ) \\ &= R_a + j \; ( \; X_S ) \end{split}$	
	<ul> <li>Where,</li> <li>Z<sub>S</sub> = synchronous impedance, R<sub>a</sub> = Armarure resistance, X<sub>L</sub> = X<sub>a</sub> = Armature reaction reactance, X<sub>S</sub> = Synchronous reacta</li> <li>iii) Distribution factor</li> </ul>	-
	It is the ratio of vector sum of the emf in the individual of	coil to the arithmetical
	sum if the coils are of concentrated type or all the coil sides are in	n only one slot.
	OR	
	$K_d = \frac{Vector \ sum \ of \ coil \ voltages \ per \ phase}{arithmetic \ sum \ of \ coil \ volatges \ per \ phase}$	
	iv) Pitch factor: It is the ratio of the voltage generated in the short pitch co in the full pitch coil.	il to the voltage generated
	OR	
	$K_{c} = \frac{Actual \ voltage \ generated \ in \ the \ short \ pitch \ coil}{Voltage \ generated \ in \ the \ full \ pitch \ coil}$	
<b>d</b> )	State the need of parallel operation of 3-ph alternator.	
Ans:	The necessity of parallel operation of Alternators :	
	( Any Four Point	expected: 1 Mark each)
	1. <b>Continuity in supply system</b> : Continuity in supply system is we have two or more altern is out of order then the power supply can be maintained with t alternator.	-
	2. More Efficiency: The alternators can be put ON or cut OFF as per the load of alternator is maximum at full load. Therefore we can put O alternators as per load demand and operate the alternators at fu	N required number of
	3. Maintenance and repair: With more number of alternators in parallel, any one can	



		Summer- 2016 Ex		
Subje	ct Code: 1'	7511 <u>Model Ans</u>	<u>wer</u>	Page 9 of 26
	<ul> <li>maintenance and repair without disturbing the supply. The smaller units are very easi repairable.</li> <li>4. Standby of reserved unit:         <ul> <li>In case of number of small alternators in parallel, The standby alternator require is also of small capacity.</li> <li>Future expansion:                 Considering the probable increasing in demand in future, some additional units are installed and can be connected in parallel.</li> <li>Saving In Fuel: Since almost all alternators are operated on full load no anyone alternator operates lightly loaded.</li> </ul> </li> </ul>			
	A J	0	K	
	Advantag	ges of parallel operation of alternator:-		
		veral small units connected in parallel of small units is disabled, the entire p	-	e large unit. If
	load	e units may be connected in service ar d on the station. This keeps the units he efficiency of the operation.		-
		of several units if one unit fails, it can ply to consumers.	n be repaired easily without th	e failure of
		litional units can be connected in para growth of the load.	llel with the resent units to con	rrespond with
	5) Co	st of the spares if any required for rep	air, maintenance will be reduc	ed.
e)		two applications of each motor : i ar induction motor iv) Stepper mot		rsal motor
Ans:		plications of each of the following:	(Each Motor Application	1 : 1 Mark)
	Sr.No	Types of Induction Motor	Applications (Any Two exp	pected)
	i)	A.C. series motor (Any Two Applications 1 Marks)	<ol> <li>Where high starting torq e.g. Electric Traction</li> <li>Stone Crushing Machine</li> <li>Washing Machines.</li> <li>Mixers and grinders</li> <li>Food processors.</li> <li>Small drilling Machines.</li> <li>In main line service</li> <li>In Electric Traction</li> </ol>	



ect Code:	17511 <u>Model Ans</u>	wer Page 10 of
ii)	Universal Motor	1) Mixer
/	(Any Two Applications 1 Marks)	2) Food processor
	(,,,)	3) Heavy duty machine tools
		4) Grinder
		5) Vacuum cleaners
		6) Refrigerators
		7) Driving sewing machines
		8) Electric Shavers
		9) Hair dryers
		10) Small Fans
		11) Cloth washing machine
		12) portable tools like blowers,
		drilling machine, polishers etc
iii)	Linear Induction Motor	
		• Application for Stationary Field Syste
	(Any Two Applications 1Marks)	
		1. Automatic sliding doors in an
		electrical train,
		2. Metallic belt conveyer,
		3. Mechanical handling equipment, su
		as propulsion of a train of tubs alon
		a certain route,
		4. Shuttle-propelling application.
		• Applications for the moving field
		system.
		1. High and medium speed application
		have been tried with linear motor
		propulsion of vehicles with air
		cushion or magnetic suspension.
		2. High speed application as a travelli
		crane motor where the field system
		suspended from loist.
iv)	Stepper Motor	1.Suitable for use with computer
	(Any Two Applications 1Marks)	controlled system
		2. Widely used in numerical control of
		machine tools.
		3. Tape drives
		4. Floppy disc drives
		5. Computer printers
		6. X-Y plotters
		7. Robotics
		8. Textile industries
		9. Integrated circuit fabrication
		10. Electric watches



Subje	ct Code: 17511 <u>Model Answer</u> Page 11 of 26
<b>f</b> )	State construction and working of shaded pole single phase induction motor.
Ans:	i) Shaded Pole Induction Motor : (Figure-2 Mark & Explanation: 2 Mark)
	1-Ph supply for the supply for the s
	Stator pole Shaded band Shaded band Shaded band Stator Wdg Squillel cage Cotor Squillel cage Squillel cage
	OR Equivalent Fig.
	Construction & Working:- When single phase supply is applied across the stator winding an alternating field is created. The flux distribution is non uniform due to shading coils on the poles. Now consider three different instants of time $t_1$ , $t_2$ , $t_3$ of the flux wave to examine the effect of shading coil as shown in the fig above. The magnetic neutral axis shifts from left to right in every half cycle, from non shaded area of pole to the shaded area of the pole. This gives to some extent a rotating field effect which may be sufficient to provide starting torque to squirrel cage rotor.
Q.3	Attempt any Four : 16 Marks
a)	The power input to a 500 V, 50 Hz, 6-pole, 3-ph induction motor running at 975 rpm is 40 kW. The stator losses are 1 kW and the friction and windage losses total 2 kW. Calculate i) The slip ii) The rotor cu-loss iii) Shaft power and iv) The efficiency.
Ans:	Given Data: 3Ph, 50 Hz I.M $P = 6$ Motor I/p = 40 x $10^3$ W $N =$ Actual Speed= 975 RPM
	Assuming , $N_s$ = 1000 RPM which is very close with N



Subje	ct Code: 17511	Summer– 2016 Examin <u>Model Answer</u>	ations Page 12 of 26
	1) The Slip:	% $Slip = \frac{N_s - N}{N_s} \times 100 = \frac{1}{N_s}$	<u>000–975</u> 1000 (1 /2Marks)
	Now,	% <i>Slip</i> = 0.025 <i>or</i> 2.5 %	(1 /2Marks)
	Gross Rotor i	i <b>nput =</b> Net Power input + Sta	ator Losses (1/2 Marks)
		= (40 KW+1 KW) watt	t
		$= 39 \text{ KW or } 39 \text{ x } 10^3 \text{ W}$	Vatts (1/2 Marks)
	2) Rotor Coppe	er Losses: S (Rotor Input)	
		= (0.025) (39 KW)	
		= 975 Watts	(1/2 Marks)
	3) Shaft Power	or Gross Rotor output = (1-	-S) (Rotor Input)
		$= (1 - 0.025)(39 \times 1)$	0 <sup>3</sup> )
		= 38025 <i>watts</i>	
	4) Net Output:	Gross Rotor output – Mechani	ical Losses
	=	= (38025) – (2000)	
	Net Output	= 36025 Watts	(1/2 Marks)
	5) Efficiency :		
	Efficie	$ency = \frac{Net \ Output}{Rotor \ Input} \times 100$	(1/2 Marks)
		$=\frac{36025}{40000}\times100$	
	Effici	<b>ency</b> = 90.06 %	(1/2 Marks)
<b>b</b> )	With neat sketch sta	te the working principle of s	tar-delta starter.
Ans:		(Wiring Dia	ngram-2 Mark & Explanation-2 Mark)
	At Star	ting, the stator winding is conr	nected in star connection.
	At the time	e of starting in star connection,	, $Iph = \frac{Vph}{Z_{sc}}$ and $Vph = \frac{V_L}{\sqrt{3}}$
	Therefore sta	arting current controlled to a sa	afe value.




Subject Code: 17511

### MAHARASHTRA STATE BOARAD OF TECHNICAL EDUCATIOD (Autonomous) (ISO/IEC-27001-2005 Certified)

# Summer– 2016 Examinations <u>Model Answer</u>

Page 13 of 26





Subject Code: 17511

Model Answer

Page 14 of 26

	-				
	4	Axial length	short	large	
	5	Diameter	large	small	
	6	Operation	noisy	Very smooth	
	7	Centrifugal stresses	Non uniform	uniform	
	8	Application	In hydro power stations	Thermal power station	
<b>d</b> )	State th alternat	6	excitation in case of par-	allel operation of two, 3-ph	
Ans:			ion in case of Two 3-ph alter	rnator is as under. Keeping	
		load on the alternator is		(4 Mark)	
	1. If the excitation of any one alternator increases, it's reactive power component increases, it's power factor decreases and the load current shared by the same alternator increases.				
		while the load current sh	the remaining alternator is that hared decreases.	a his power factor mercuses	
<b>e</b> )	How the	e direction of rotation o	f capacitor start capacitor r	un motor can be reversed?	
Ans:	Reason	for capacitor start and	capacitor run can be rever	sed: (4 Mark)	
	Single phase motors have two windings, the main winding and the auxiliary winding. The auxiliary winding is used to start the motor and may be disconnected once the motor picks up sufficient speed. Reversing a single phase motors cannot be done by reversing the polarity of the supply to the entire motor. To reverse the single phase motor, the polarity of the supply				
	to or	nly one of the windings	needs to be changed.		
	term	This can be done by inal box of the motor.	reconfiguring special links w	hich may be provided in the	
<b>f</b> )	What is	the working principle	of linear induction motor		
Ans:			ation linear induction motor	(Working – 4 Marks) r:-	
	<ul> <li>Linear Induction Motor (LIM) is an asynchronous motor, working on the same principle an Induction motor works, but is designed to produce the linear motion,</li> </ul>				




Subj	Summer-2016 Examinationsct Code: 17511Model AnswerPage	15 of 26
	When the stator (primary) is excited by applying 3 phase supply in an induct motor, rotating magnetic field is produced.	ion
	Here, after laying down the stator flat, excitation with three phase supply wo induce a 'travelling flux', a travelling magnetic field, which would linearly tr along the stator.	
	This would again induce emfs in the rotor, which produces a forward thrust the and if the secondary (rotor) is fixed primary is free to move, it would travel the length of the machine linearly, along the tracks provided so produce the motion.	across
Q.4	Attempt any Four: 16 Mar	rks
<u>a)</u>	State why three phase induction motor never runs on synchronous speed.	andra)
Ans:	(4 Ma)	
	The working principle of three phase induction motor is based on relative	
	between rotating magnetic field and rotor conductors i.e (N <sub>s</sub> - N), According to Le	
	rotor will try to catch the synchronous speed of rotating magnetic field to oppose t	he 'cause
	producing it'. But rotor never succeeds due to frictional losses.	
	If rotor catches the synchronous speed of rotating magnetic field, $(N_S - N)$ i.e	relative
	motion will be zero and rotor stops to rotate and therefore three phase induction m	otor can
	never run on synchronous speed.	
b)	State how each of the following can reduce starting current of 3-ph induction r By inserting resistance in rotor winding. ii) By connecting autotransformer winding.	
Ans:	i) By inserting resistance in rotor winding can reduce starting current of 3 pha	
	(2) This method is only applicable to slip-ring motors. At the instant of starting	Marks) o. the
	external rotor resistance can be kept at maximum value. Therefore heavy starting	
	can be controlled.	current
	ii) By connecting autotransformer in stator winding: (2	Marks)
	$\blacktriangleright$ At the instant of starting, the position of the slider/variable tap is kept at z	ero
	voltage position.	
	> When the slider moves gradually in clockwise direction, the voltage applied	ed to



Subje	ct Code: 17511 Summer– 2016 Examinations	Page 16 of 26
	three phase induction motor will be increased in steps.	
	> At starting reduced voltage can be applied to 3-phase induction mo	tor and hence
	heavy starting current will be reduced or controlled.	
	<ul> <li>When motor start to rotate and achieve about 70 % of the rated spectrolized can be applied to 3-phase induction motor.</li> <li>Thus by using 3-phase auto transformer as a starter, starting current controlled.</li> </ul>	
<b>c</b> )	Derive the emf equation of an alternator.	
Ans:	EMF Equation of alternator :	
	Let, $P = No.$ of rotor poles. $\phi = Flux$ per pole $Z = Number of stator conductor N = Speed in rpm$	
	$\therefore turns \ per \ phase \ (Tph) = \frac{Z_{Ph}}{2} \$	(1/2 Marks)
	$\therefore$ Frequency of induced emf is	
	f = Cycles per rotation x rotation per sec	
	$\therefore = \frac{P}{2} \times \frac{N}{60}$	
	2 00	
	$\therefore f = \frac{PN}{120}$	(1/2 Marks)
	Consider one rotation of rotor then change in flux linkage is,	
	$d\phi = P. \phi$ Time required for one rotation is,	
	$\therefore dt = \frac{1}{n} = \frac{1}{(N/60)} = \frac{60}{N} Sec.$	(1/2 Marks)
	By faradays law of Electromagnetic induction	
	$\therefore Average \ emf \ per \ conductor = \frac{d\phi}{dt}$	
	$\therefore E_{\text{ave}} / \text{Conductor} = \frac{P.\phi}{(N/60)}$	
	$\therefore E_{ave} / Conductor = \frac{P \times \phi \times N}{60} Volt Volt$	(1/2 Marks)
	$\therefore E_{\text{ave}} / \text{turn} = 2 E_{\text{ave}} / \text{Conductor} \frac{P \times \phi \times N}{60} V_{0}$	olt
	$\therefore E_{\text{ave}} / \text{turn} = 2 \frac{P \times \phi \times N}{60} Volt$	
	$\therefore \qquad = \frac{4P\phi N}{120} Volt Volt$	(1/2 Marks)







Subject Code: 17511

Model Answer

Page 18 of 26

e) [	points)	e resistance split j		
	S.No	Points	Resistance split pha motor	(Each Point -1 Mark ) ase Capacitor split phase motor
	i)	Output	Low	High
Ans:	ii)	Starting torque	Low	High
	iii)	Power factor	Low	High
	iv)	Applications	Washing Machine, Fans Blowers, Centrifugal Pu Small electrical Tools e	amp, Refrigerator, Air
	State the	working principl	e of permanent magnet s	stepper motor.
Ans:	Permane	nt Magnet Steppe	er Motor:-	Figure 2 Mark & Working 2 Mark)
	20 (F	PhA N O DhD S PhC C2 C2	PhB oB <sub>1</sub> or AA'a	A Az Stator slots Stator wdg Permanant magne Bz rotor poles. A4 A3 A4 B3 MBB' are the two phases
		Permanent Mag Rotor Coils	N S	Motor Case



# Summer-2016 Examinations **Model Answer** Subject Code: 17511 Page 19 of 26 Working :-When we gives supply to stator's winding. There will be a magnetic field developed in the stator. Now rotor of motor that is made up of permanent magnet, will try to move with the revolving magnetic field of stator. This is the basic principle of working of stepper motor. OR If the phase is excited in ABCD, due to electromagnetic torque is developed by interaction between the magnetic field set up by exciting winding and permanent magnet. Rotor will be driven in clockwise direction. **Q.5** Attempt any Two : 16 Marks An 18.65 kW, 4 pole, 50 Hz, 3-phase induction motor has friction and windage losses of 2.5 percent of the output. The full load slip is 4%. Compute for full load a) a) The rotor cu loss b) The rotor input c) The shaft torque d) The gross torque. **Given Data:** Ans: 3Ph, 4 Pole, 50 Hz I.M Full load Slip = 3.5 % Net motor o/p = 18.65 kW I.M $S_f = slip at full load = 0.04$ Windage losses = 0.025 Windage & frictional losses (Mech. Losses) = $0.025 \times 18.65 \times 10^3$ $= 466.25 \ watts \ \cdots \ (1/2 \ Marks)$ Gross (Net) Rotor output = Net motor output + mech. losses------ (1/2 Marks) = 18650 + 466.25 $= 19116.25 \text{ watts} - \cdots (1/2 \text{ Marks})$ Rotor Input = $\frac{19116.25}{(1-0.04)}$ = 19912.75 *Watts* ------ (1/2 Marks) Rotor Input = 19912.75 Watts ii) Rotor Copper Losses = S × Rotor Input ------ (1/2 Marks) Rotor Copper Losses = $0.04 \times 19912.75$ Rotor Copper Losses = 796.51 *Watts* ------- (1 /2Marks) $N_s = \frac{120 f}{P} = \frac{120 \times 50}{4} = 1500 \, RPM$ ------- (1/2 Marks)




Subje	Summer- 2016 Examinationsct Code: 17511Model Answer	Page 20 of 26
	Full Load Speed = Ns $(1-S)$ ,	
	Full Load Speed = 1500 (1-0.04)	
	Full Load Speed = 1440 RPM	
	N in RPS = $N = \frac{1440}{60} = 24 RPS$	(1 Marks)
	iii) Gross torque =	
	$=\frac{Gross output}{2 \pi N}  (Where, N in RPS) $	(1/2 Marks)
	$=\frac{19912.75}{2\times 3.142\times 24}$	
	$T_g = 126.75 N - m$	(1 Marks)
	iv) The shaft torque or Net torque =	
	$=\frac{Net \ output}{2 \ \pi \ N}  (Where, N \ in \ RPS)  \cdots$	(1/2 Marks)
	18650	
	$=\frac{18650}{2\times3.142\times24}$	
	$T_{sh} = 123.66 \ N - m$	(1 Marks)
b)	A certain 3-ph, star connected, 100 kVA, 11000 V alternator has rate A. The a.c. resistance of the winding per phase is 0.45 ohm . The test below : O.C. Test — Field current = 12.5 A; Voltage between lines = 42 S.C. Test — Field current = 12.5 A, line current is equal to 52. Determine the full load voltage regulation of the alternator at p.f. 0. p.f. leading.	results are given 22 V 5 A.
Ans:	Given Data: 3-Ph, 100 KVA, 11 KV star connected alternator,	
	$V_T$ Line 11000 KV ( $V_T/ph=6350.85$ )	
	$I_{a} \ line \ Current = \frac{KVA \times 10^{3}}{(\sqrt{3}) \times (V_{TLine})}$	(1/2 Marks)
	$I_a \ line \ Current = \frac{(100) \times 10^3}{(\sqrt{3}) \times (11) \times 10^3}$	



Subject Code: 17511	Summer– 2016 Examinations <u>Model Answer</u>	Page 21 of 26
I <sub>a</sub> li	<i>ine Current</i> = 5.25 <i>A</i>	(1/2 Marks)
	$Ph = \frac{O.C. \text{ Voltage}}{S.C.Current/ph} \text{ at } I_F = 10A - \cdots$ $Ph = \frac{422/\sqrt{3}}{52.5}$	(1/2 Marks)
Z	$P_s/Ph = 4.64  \Omega$	(1/2 Marks)
X <sub>s</sub> /I	$Ph = \sqrt{(Z_{s} / ph)^{2} - (R_{a} / ph)^{2}}$	(1/2 Marks)
X	$T_s /Ph = \sqrt{(4.64)^2 - (0.45)^2}$	
X Now,	$V_{s}/Ph = 4.62 \ \Omega$	(1/2 Marks)
	full load for 0.8 Lagging P.f :	
E/ph	$=\sqrt{\left(V_{T} \cos \phi + I_{a} R_{a}\right)^{2} + \left(V_{T} \sin \phi + I_{a} X_{S}\right)^{2}}$	(1Marks)
$E/ph = \sqrt{[(63)]}$	$(550.85)(0.8) + (5.25)(0.45)]^2 + [6350.85)(0.6) + (500)^2$	$(5.25)(4.62)]^2$
E/ph = 6367.3	32 Volt	(1/2 Marks)
% Regulat	$\mathbf{ion} = \frac{\mathbf{E}_0 / \mathbf{ph} - \mathbf{V}_T / \mathbf{ph}}{\mathbf{V}_T / \mathbf{ph}} \times 100 $	(1 Marks)
% Regulat	$\mathbf{ion} = \frac{6367.32 - 6350.85}{6350.85} \times 100$	
_	ion = 0.2593 % at full load for 0.8 Lagging P.f;	(1/2 Marks)
No. loa	$d emf E_0 = \sqrt{(V_T \cos\phi + I_a R_a)^2 + (V_T \sin\phi - I_a)^2}$	$(X_s)^2$ (1Mark)
No. loa	d emf $E_0 = (6350.85 \times 0.8 + 5.25 \times 0.45)^2 + (6350.85 \times 0.8 + 5.25 \times 0.8 + 5.25 \times 0.45)^2 + (6350.85 \times 0.8 + 5.25 \times 0.45)^2 + (6350.85 \times 0.8 + 5.25 \times 0.45)^2 + (6350.85 \times 0.8 + 5.25 \times 0.8 + 5.25 \times 0.45)^2 + (6350.85 \times 0.8 + 5.25 \times 0.8 + 5.25 \times 0.8 + 5.25 \times 0.45)^2 + (6350.85 \times 0.8 + 5.25 \times 0.8 + 5.25 \times 0.8)^2 + (6350.85 \times 0.8 + 5.25 \times 0.8)^2 + (6350.85 \times 0.85 \times 0.8)^2 + (6350.85 \times 0.85 \times 0.85 \times 0.8)^2 + (6350.85 \times 0.85 \times 0.85$	$50.85 \times 0.6 - 5.25 \times 4.62^2$
No. loa	$d \ emf \ E_0 = \sqrt{(25837321) + (14335689.06)}$	







Subject Code: 17511	Summer– 2016 Examinations <u>Model Answer</u>	Page 23 of 26
Where	$N_s = \frac{120 f}{P} = \frac{120 \times 50}{6} = 1000  RPM $	(1 Marks)
	Full Load Speed = Ns $(1-S)$ ,	
	Full Load Speed = 1000 (1-0.4)	
	Full Load Speed = 960 RPM	(1/2 Marks)
1) Gross Roto	or Output = $2 \pi N T_g$ (Where, N in RPS)	
	$=2 \times 3.142 \times \frac{960}{60} \times 149.3$	
	=15011.22 Watts	(1/2 Marks)
Net Mo	otor output = Gross Rotor output – mech. Losses	(1/2 Marks)
	= 15011.22 - 200	
Net M	otor output = 14811.22 Watts	(1/2 Marks)
2) Rotor Input	$= \frac{Gross \ Rotor \ output}{(1-S)}$	(1 Marks)
Rotor Input	$=\frac{15011.22}{(1-0.04)}=15636.69 Watts-$	(1/2 Marks)
Rotor Copp	er Losses = $S \times Rotor$ Input	(1/2 Marks)
Rotor Copp	er Losses = 0.04×15636.69	
Rotor Cop	<b>per Losses =</b> 625.47 <i>Watts</i>	(1/2 Marks)
3) Net Motor In	nput = Rotor Input + Stator Losses	
Net Motor It	mput = 15636.69 + 1620 Watts	
Net Motor In	nput = 17256.69 <i>Watts</i>	(1/2 Marks)
	% $\eta = \frac{Net \ Motor \ output}{Net \ Motor \ Input} \times 100$	(1 Marks)
	% $\eta = \frac{14811.22}{17256.69} \times 100$	
	% $\eta = 85.82$ %	(1 Marks)



# Summer-2016 Examinations **Model Answer** Subject Code: 17511 Page 24 of 26 Describe the factors affecting the regulation of three phase alternator and draw the phasor diagrams of loaded alternator when operating power factor is lagging and **b**) leading. Factors affecting the regulation:-( Any Two point expected : 2 Marks) Ans: 1. It depends on armature resistance $(R_a)$ 2. It depends on leakage reactance $(X_{I})$ 3. Magnitude of load current 4. Magnitude of Power factor of load 5. Type of load Power factor (Lagging, leading, Unity) 6. Effect of armature reaction $(X_{a})$ i) Lagging Phasor diagrams of loaded alternator: (3 Marks) Lagging Power Factor Phasor Diagram Voltage Regulation at Lagging Power Factor OR or equivalent figure ii) Leading Phasor diagrams of loaded alternator: (3 Marks) $E_2$ I.R. Leading Power Factor $V_2$ Phasor Diagram Voltage Regulation at Leading Power Factor OR or equivalent figure



Subje	ct Code: 17511 <u>Model Answer</u>	Page 25 of 26
c)	A certain 3-ph alternator is rated at 5 kVA, 110 V, 26.3 A, 50 Hz and stator resistance between terminals as measured with d.c. is 0.2 ohm . W rated speed, the stator line voltage is 160V for a field current of 4A. At r short circuit stator current per terminal is 60A for a field current of 4A. Calculate: i) Synchronous impedance per phase ii) The voltage regulation at 0.8 p.f. lagging. The alternator is star connected.	ith no load and ated speed, the
Ans:	<b>Given Data:</b> 3-Ph, 5 KVA, 110 KV star connected alternator, Ra = 0.2 ohm (d.c)	26.3 A
	50 Hz and 1200 rpm	
	O.C. Voltage = 160 V ( Line) S.C Current = 60A for $I_F = 4$ A	
	1. $V_{o.c}$ line Volatge = 160 V	
	$V_{oc}$ Phase voltage $= \frac{160}{(\sqrt{3})}$	
	$V_{oc}$ Phase voltage = 92.38 V	(1/2 Marks)
	2) The Synchronous impedance per Phase:	
	$Z_s / Ph = \frac{O.C. Voltage}{SC. Current / ph}$ for the same $I_F$	(1/2 Marks)
	$Z_{s}/Ph = \frac{92.38}{60}$	
	$S_{s} = 60$ $Z_{s} / Ph = 1.54  \Omega$	(1 Marks)
	3) Armature resistance per Phase : <b>Given</b> := $R_a = 0.2$ ohm between the ter min als (d.c value) 0.2	
	$\therefore R_a/ph = \frac{0.2}{2} = 0.1 \text{ ohm } (\text{ d.c value})$	
	:. Considering the skin effect, the a.c. value of $R_a/ph$ is given by = $1.5 \times 0.1$	= 0.15 <i>ohm</i>
	4) Synchronous Reactance per phase:	
	$X_{s} / Ph = \sqrt{(Z_{s} / ph)^{2} - (R_{a} / ph)^{2}}$	(1/2 Marks)
	$X_{s} / Ph = \sqrt{(1.54)^{2} - (0.15)^{2}}$	
	$X_{s} / Ph = 1.5327 \ \Omega$	(1 Marks)



Subject Code: 17511	Summer– 2016 Exa <u>Model Answ</u>		Page 26 of 26
V line Vo	blatge = 110 V		(1/2 Marks)
V line V	$Volatge = \frac{110}{(\sqrt{3})}$		
V line V	<i>Volatge</i> = 63.51		(1/2 Marks)
$\therefore  Cos\phi = 0.8 \ lag$	$Sin\phi = 0.6$ and $Ia = 26.3$	3A = Assuming f	ùll load conditio
Now,			
% Regulation at fu	Ill load for 0.8 Lagging P.	f :	
$E_0 = $	$(V \ Cos\phi + I_a R_a)^2 + (V \ Si$	$n\phi + I_a X_s)^2$	(1Marks)
$E_0 = $	[(6.51)(0.8) + (26.3) (0.15)	$]^{2} + [63.5)(0.6) + (26.3)(1.53)$	327)] <sup>2</sup>
$E_0 = $	[(2997.89) + (6148.13)		
$E_0 = 95$	5.63 <i>Volt</i>		(1/2 Marks)
% Regulation	$\mathbf{n} = \frac{E_0 - V}{V} \times 100$		(1 Marks)
% Regulation	$\mathbf{n} = \frac{95.63 - 63.51}{63.51} \times 100$		
% Regulation	<b>n</b> = 50.57 %		(1 Marks)

-----END-----