



SUMMER – 15 EXAMINATIONS


Subject Code: **17622**

Model Answer


Important Instructions to examiners:

- 1) The answers should be examined by key words and not as word-to-word as given in the model answer scheme.
- 2) The model answer and the answer written by candidate may vary but the examiner may try to assess the understanding level of the candidate.
- 3) The language errors such as grammatical, spelling errors should not be given more importance. (Not applicable for subject English and Communication Skills)
- 4) While assessing figures, examiner may give credit for principal components indicated in the figure. The figures drawn by candidate and model answer may vary. The examiner may give credit for any equivalent figure drawn.
- 5) Credits may be given step wise for numerical problems. In some cases, the assumed constant values may vary and there may be some difference in the candidate's answers and model answer.
- 6) In case of some questions credit may be given by judgment on part of examiner of relevant answer based on candidate's understanding.
- 7) For programming language papers, credit may be given to any other program based on equivalent concept.

Q. NO.	MODEL ANSWER	MARKS	TOTAL
1	Attempt any FIVE:	5*4	20
a	<p>Various stage involved in basic shearing process:</p> <p>Stage 1: As the top cutting member is moved downwards and brought to bear on the metal with continuing pressure, the top and bottom surfaces of the metal are deformed.</p> <p>Stage 2: As the pressure increases the internal fibres of the metal are subjected to deformation. This is plastic deformation prior to shearing.</p> <p>Stage 3: After a certain amount of plastic deformation the cutting member begin to penetrate. The uncut metal work hardens at the edges.</p> <p>Stage 4: Fractures begin to run into this work hardened metal from the points of contact of the cutting members. When these fractures meet, the cutting members penetrate the whole of the metal thickness.</p>	<p>02 marks for diagram</p> <p>0.5 mark</p> <p>0.5 mark</p> <p>0.5 mark</p> <p>0.5 mark</p>	<p>04</p>

<p>b</p>	<p>Shear Type Nibbler:</p>  <p>The shear type nibbler: This portable power tool is used for rapid and accurate straight line or curved cutting of material up to 4.5mm thickness. It is basically a short stroke power shear fitted with a rapidly reciprocating cutting blade, so that each stroke makes a cut approximately 3mm in length.</p> <p>The shear type nibbler is fitted with a pair of very narrow flat blades, one of which is usually fixed and the other moving to and from the fixed blade at fairly high speeds. Generally these blades have a very pronounced Rake to permit piercing of the material for internal cutting, and since the blades are so narrow, the sheet material can be easily manoeuvred during cutting.</p> <p>The top blade is fixed to the moving member or ram and the bottom blade on a spiral extension or 'U' frame. This extension is shaped like the body of a 'throatless shear', to part the material after cutting.</p> <p>There is usually provision for vertical adjustment to allow for re-sharpening of the blade by grinding and an adjustment behind the bottom blade to allow for setting the cutting clearance.</p> <p>figure above shows details of the 'shear type nibbler'.</p> <p>The spiral U-frame is designed to assist in parting the metal after it has been sheared.</p> <p style="text-align: center;">OR</p>	<p>Any one type</p> <p>02 marks for diagram</p> <p>02 marks for expln.</p>	<p>04</p>
----------	--	--	-----------

The punch type nibbler:





02
marks
for
diagram

This portable nibbling machine does not operate on the same principle as the shear type. A punch and die is employed instead of shearing blades and the nibbling principle is a special application of punching. The advantage of these machines is that they will effect certain operations that cannot be accomplished on other shearing machines. For example, they may be used to cut out apertures which could only otherwise be produced by means of specially designed punches and dies set up in a powerful press. These portable power tools are used for rapid and accurate straight line or curved cutting of material from approximately 1.62mm to 3.2mm thickness. Like the shear type machine the top cutting tool (a punch) reciprocates at fast short strokes. Punch type nibblers are available, in various sizes and the punch reciprocates at a rate of 350 to 1400 strokes per minute over a die nibbling out the material by the simple principle of overlapping punching and only a slight finishing is necessary to produce


02
marks
for
expln.




e	Parameters	Advantages over power press	Disadvantages over power press	02 marks for each point	04
	Fly press	Simple in construction and operation	Simple piercing, blanking and similar operations. Fitting, assembling, punching and embossing thin sheets below 1mm thickness only.		
		It is very versatile. Tool changing is rapid and simple. With the correct tooling one can punch coin, tube end form, bend, slot, form, dimple, clinch fasteners, edge fold, rubber form, etc.	Mass production for a particular tooling arrangement is possible but time consuming due to human intervention.		
		Etc.	Etc.		
f	Pre-forming of ends is an operation prior to rolling of plates and sheet metals in order to remove flats at the two meeting edges after rolling.		02 marks	04	
The need is to obtain a true cylinder without flats where the opposite edges touch.		02 marks			
g	<p>High strength friction grip bolts (HSFG): HSFG Bolts are of high tensile strength and used in conjunction with high strength nuts and hardened steel washers in structural steel works. The bolts are tightened to a specified minimum shank tension so that transverse loads are transferred across the joint by friction between the plates rather than by shear across the bolt shank. These bolts have high yield strength. They should conform to IS: 3757-1985. They are tightened by torque wrenches and require hardened washers to induce initial tensions, which causes friction between the plate surfaces. Due to friction, there is no slip in the joint and therefore the joints with HSFG bolts are called friction type or non-slip type joints.</p> <p>These bolts are made by a special cold working process which includes two operations: heading and thread rolling. Close tolerances ensure accuracy and heat treatment is carried out afterwards. The surfaces in contact must be free from paint, oil, dirt, loose rust and scale.</p> <p>Clearance --- The diameter of the bolt hole is usually 1.6mm larger than the nominal diameter bolt shank.</p>		02 marks	04	
		01 mark			
		01 mark			

2	Attempt any two:	8*2	16
a	<p>(i) POP Rivet:</p>  <p>There are many other kinds of rivet used for joining sheet metal but the pop rivet is one of the most popular. It is fitted into the drilled hole and formed either by using lazy tongs or a plier type tool. Applications are in assembly of light fabrications, vehicle panels, ductwork and containers, used for all open blind riveting locations for normal materials with no structural or access problems.</p> <p>The rivet is a hollow tube of relatively soft material with a formed head on one side. The rivet is pre-assembled on a headed mandrel made from a stronger material than the rivet, the plain end of the mandrel projecting a relatively high distance through the head of the hollow rivet.</p> <p>The rivet shank is inserted through the hole in the parts to be joined such that it projects a set distance out of the far end of the hole. The mandrel is pulled through the rivet using a special tool causing the projecting end to be upset. The mandrel is engineered to snap at a set tension resulting in the correct formed head on the far side and the joint being under compression.</p> <p>(ii) Bifurcated Rivet:</p> 	<p>02 marks for diagram</p> <p>02 marks for (expln.)</p> <p>02 marks for diagram</p>	<p>08</p>

	<p>The rivet shank is split in two parts made of relatively soft material with a formed head on one side. The rivet shank is inserted through the hole in the parts to be joined such that it projects a set distance out of the far end of the hole. The mandrel is inserted from top and pushed with a blow of hammer due to which the bifurcated end of rivet on other side gets split outwards and other side is locked.</p>			02 marks for (expln.)	
b	Parameters	Bolting	Riveting	02 mark each	08
	Cost	Low cost	High cost		
	Reliability	Less	High		
	Labor skills	Unskilled to semi - skilled	Semi – skilled to skilled		
	Joint strength	Low (fluctuating loads)	High (fluctuating loads)		
c	<p>For Huge Smith Vertical plate bending machine:</p> <ul style="list-style-type: none"> • For bending cylinders from large to small diameters used in the production of pressure vessels, boilers, nuclear plant and legs/piles for oil platforms and modules • Sizes from 300 – 5000 Tonnes or more for plate widths up to 4.5 meters and thicknesses to 200mm cold • The vertical machine requires minimum crane attendance and occupies minimum floor space • Complete cylinders can be formed in a floor to floor time of 20 mins or less depending on diameter • Plate edge pre-setting is easily carried out using the direct acting hydraulic force of the machine • Adjustable bending centres provide the most suitable conditions for bending all sizes and thicknesses of plates • Crane attendance is not required once the plate is entered into the machine • RE-rounding and correction of weld seam can easily be carried out • Machine can be used to form cones and for plate straightening and also can be used for heavy duty flanging work including closed boxes <p>A vertical angle ring bender is shown below for pictorial representation purpose only;</p>			04 marks (expln.)	08

3	Attempt any four:	8*2	16
a	<p>Treadle Guillotine Machine:</p>  <p>1- Foot pedal, 2- Rest for sheet, 3- Table, 4- Slide holding blade, 5- Hold down attachment, 6- Side wall</p> <p>The treadle operated guillotine shearing machine is economical to be use in small metal shop for cutting sheets. The sheet up to 1.5mm(16swg)thick are cut into strips. The blade has 4 working edges which provided 4 times cutting life of the blade.</p> <p style="text-align: center;">OR</p>	<p>any one guillotine machine</p> <p>02 marks for diagram</p> <p>02 marks</p>	<p>08</p>

Power/Motorised Guillotine Machine:



02
marks
for
diagram

Motorised shearing machine:

1. table,
2. Hold down attachment (Pressure Pad)
3. slide
4. Table
5. Main gear and its cover
6. Driving motor with cover

Parts of motorised shearing machine slide:

This carries the top blade or blades. In the machine where the working length is large the number of blade segments is more than one. This is named as upper bar also.


- i) Blades: Blade actually cuts the sheet. It is like flat finished bar. All four edges are provided clearance for efficient cutting, thereby avoids frequent stoppages for regrinding. These are fixed with help of screws and are made of high carbon steel or high speed steel.
- ii) Hold down attachment: This attachment is used to grip the sheet before it is cut and operates simultaneously.
- iii) Table: The sheet is brought over here for cutting. It is fitted with front gauge and side gauge for squaring. Adjustable back gauge is carried on slides.
- iv) Side walls: The side walls are fabricated or cast which support the table and are braced by stay rods fastened to the table. They are designed to withstand operational cutting forces and provide stability to machine for long life without showing any sign of cracking or

02
marks
for any
two
parts

deformation.

v) Clutch: The clutch is fitted to the press along with the main gear to engage every time the pedal is pressed. The cutting process is continuous so long the pedal is pressed and disengages immediately no sooner the pedal is released.

Working:





When power is transmitted to the blade it starts moving downward. A sufficient clearance is provided between the bottom and top blade. The top blade is inclined at a considerable angle called as shear angle which is approximately 5° with horizontal because of which area under shear is greatly reduced and consequently the force required to shear the material is also considerably reduced

Shear Force = Area under shear X Shear strength of material



A typical guillotine machine is provided with fixed side gauge extension arm, adjustable front gauge, table or bed and bottom blade as shown in figure. The sheet to be cut is held against fixed side gauge and the front and back gauges are adjusted according to the required dimension of sheet to be cut.

02
marks
for diag.


02
marks
for
expln.

b	<p>Cropping</p>  <p>(a) Shearing plate</p>  <p>Examples of cropping</p> <p>Cropping: Cutting by shearing is quick and probably the most economical production method. The shearing of rolled steel sections is performed in dies designed to suit the section. The dies are mounted in a special shearing machine. This operation is commonly referred to as cropping.</p>	<p>02 marks for any one diag</p> <p>02 marks for expln.</p>	08
---	---	---	----

Notching:




02
marks
for any
one
diagram

	 <p>(Angle-section)</p> <p>(e) Typical mitre cutting operations performed on section cropper</p> <p>(Tee - section)</p> <p>Cutting operations (sections)</p> <p>Notching is removal of material by making a notch. In most fabrication shops, cutting operations on rolled steel sections are carried out on power machines. Machines are available which perform a combination of cutting operations, such as punching, shearing and notching, the shearing operations including not only section shearing, but round and square bar cropping and plate shearing. Angle section has to be notched in order to permit it to be bent and most of the notches are of the 'V' notch or the square-notch type.</p>	<p>02 marks for expln.</p>	
c	<p>Metal sawing is one of the important cutting operations chiefly concerned with cutting bar stock to a convenient length or size for machining. In metal sawing, the individual teeth of the saw “track” through the work, each tooth deepening the cut made by the preceding tooth in the direction of feed. Either the saw or the work may be fed and by controlling the direction of feed, either straight or curved cut can be produced. The width of the cut is approximately equal to the width of the saw itself.</p> <p>Safety Precautions for reciprocating power hacksaw:</p> <ul style="list-style-type: none"> •Cutting teeth and the blade should be positioned to cut on the draw stroke. •Blade should be so tightened that the tension is adequate to hold the blade firmly during the cutting operation. •Blade pins should be checked regularly to ensure that they are not being sheared. •The work piece should be tightened securely. 	<p>04 marks</p> <p>04 marks for any 04 points</p>	08

	<ul style="list-style-type: none"> •Ends of long pieces, projecting from the power hacksaws must be supported using a roller stand. •Cut-off sections must be cooled before handling to avoid burns and cuts from burred pieces. •Cutting fluid must be directed towards the cutting area and cutting saw teeth. •Before starting the power hacksaw, blade must be moved away from the work. •Cutting fluid and reservoir must be kept clean. Regular testing for the ratio of water and oil and correcting of fluid ensures that the evaporation of liquid does not change the efficiency of the cutting fluid. 		
4.	Attempt any two:	8*2	16
a	<p>Single cutting support: This simple device may either be a 'spade support' or a single 'roller guide' which can be adjusted vertically for 'standoff'. The figure below shows a single cutting support used in conjunction with a 'straight edge'.</p> <p>Fig 7</p>	04 marks (expln.)	08
		04 marks (diag.)	


<p>b</p>	<ol style="list-style-type: none"> 1. The centre of the rivet head is heated until bright cherry red, and the edge of the hole becomes clearly visible (A) 2. The cutting oxygen jet is turned on, and with the torch slightly inclined towards the centre, a cut is carefully made around the edge of the hole, without damaging it (B) 3. On reaching the halfway point the cut is made towards the centre (C) 4. With the cutting torch slightly inclined inwards complete the cut around the edge of the hole (D) 5. The rivet is easily removed by knocking out with a sharp hammer blow on a solid steel punch, as indicated in (E) 	<p>04 marks (diag.) & 04 marks (expln.)</p>	<p>08</p>
----------	--	---	-----------

<p>c</p>	<p>Bending operations:</p> <p>(a) Four-way dies</p> <p>(b) Acute angle tools</p> <p><i>Interchangeable four-way dies-Fig. (a).</i> The interchangeable female dies are used for bending medium and heavy plate. They are provided with 85° openings on each of the four faces.</p> <p>Male punches for use with four-way dies are usually made with a 60° angle.</p> <p><i>Acute angle dies-Fig. (b).</i> Acute angle dies have many uses and, if used in conjunction with flattening dies, a variety of seams and hems may be produced on sheet metal.</p> <p>These are available for any angle, but if the female die is less than 35° the sheet tends to stick to the die.</p> <p>Acute angle dies may be set to bend 90° by adjusting the height of the ram.</p>	<p>02 marks for each diag. and 02 marks for each expl.</p> <p>(Any Two operations)</p>	<p>08</p>
----------	--	--	-----------




c) Goose neck punch

The Goose-neck punch-Fig. (c). When making a number of bends on the same component, clearance for previous bends has to be considered. Goose-neck punches are specially designed for the above purpose. These tools are very versatile, enabling a variety of sheet metal sections to be formed.




d) Flattening

Flattening (planishing) tools-Fig. (d). Flattening tools of various forms may either be used in pairs for flattening a returned edge, or hem, on the edge of sheet metal or in conjunction with a formed male or female die



e) Radius bending


Radius bending-Fig.(e). A radius bend is best formed in a pair of suitable tools: The radius on the male punch usually slightly less than that required to allow for 'spring back' in the material.
A large radius can be produced by simply adjusting the height of the ram and progressively feeding the sheet through the tools.



f) Channel forming


Channel dies-Fig.(f). Channel dies are made with 'pressure pads' so that the metal is held against the face of the male die during the forming

operations. As a general rule, channel dies are only successful on sheet metal up to and including 2.64 mm thickness.
A channel in heavy gauge metal is best made in a 'Vee' die with a 'Goose-neck' type of male punch.






(g) Box making

Boxmaking fig.(g). Male punches for box making must be deep as possible. Most standard machines are fitted with box dies which will form a sheet metal box 170 mm deep. If deeper boxes are required, the machine must be provided with greater die space and longer male dies. For each extra 25 mm of die space the depth of the box is increased by 17 mm.

	 <p>(h) Beading (see stiffening of sheet metal)</p>		
5	<p>Attempt any two:</p>	8*2	16
a	<p>When a bending force is gradually applied to a workpiece under free bending conditions, the first stage of bending is elastic in character. This is because the tensile and compressive stresses that are developed on opposite faces of the material are not sufficiently high to exceed the yield strength of the material. The movement or strain which takes place as a result of this initial bending force is elastic only, and upon removal of the force the workpiece returns to its original shape.</p> <p>As the bending force is continued and gradually increased, the stress produced in the outermost fibres of the material eventually exceeds the yield strength.</p> <p>Once the yield strength of the material has been exceeded, the movement or strain which occurs is plastic. This permanent strain occurs only in the outermost regions furthest from the neutral plane. Between the outermost fibres and the neutral plane there is a zone where the strain produced is elastic.</p> <p>On release of the bending force, that portion adjacent to the neutral</p>	<p>01 mark</p> <p>01 mark</p> <p>01 mark</p> <p>01 mark</p>	08

	<p>plane loses its elastic stress, whilst the outer portions, which have suffered plastic deformation, remain as a permanent set. Thus the elastic recovery of shape in this zone on removal of the bending force is known as 'springback'.</p>	<p>01 mark</p> <p>01 mark</p> <p>01 mark</p> <p>01 mark</p>	
<p>b</p>	<p>Edge Bending:</p> <p>edge bending; (1) before and (2) after bending</p> <p>In edge bending a flat punch forces the stock against the vertical force of</p>	<p>02 marks for diagram</p> <p>01 marks</p>	<p>08</p>

	<p>the die. The bend axis is parallel to the edge of the die and the stock, is subjected.</p> <p>Explanation: In this method the sheet is placed on the die. Pressure pad holds the sheet as well as guides the punch when it moves downwards. Due to pressure of punch the sheet is deformed and it is bent around the die edge.</p> <p>Important points to be considered during bending operation are :</p> <ol style="list-style-type: none"> 1) Make sure the metal is having proper ductility. 2) All sheet metal processes must consider the factor of spring back 3) Proper selection of punch, blank holder, blank and part support for given blank material. 4) Optimum tension stress and compressive stress occurring on outer and inner surfaces of metal after bending. 5) While bending in press brake, selection of proper die ratio. 6) Application of proper range of punch pressure during bending. 7) Selection of allowable inner radius for obtaining crack free bends. 	<p>01 marks</p> <p>04 marks for any 04 points</p>	
<p>c</p>	<p>Inclined Shaft Rotary Shearing Machine:</p>  <p>Construction: In this type of machine the rotary cutters are inclined as shown in fig. The edge of cutter must overlap by the small amount consistent with clean cutting. There is handle provided which provides rotary motion to bevel gear, which in turn rotates the cutters.</p>	<p>02 marks for diag.</p> <p>02 marks</p>	<p>08</p>

	<p>Working: When the handle is rotated it drives the cutters. The sheet is moved to get the desired cut. Because of bevel gears the motion is transmitted at inclined position.</p> <p>Advantages: 1) The main advantage of these types of machine is that the sheets of irregular shapes can be cut depending on the skills of operator. 2) There is no restriction on the length of cut. 3) The cutters rotate producing a continuous cutting action with very little distortion of the material. 4) These machine may be hand or power driven.</p>	<p align="center">02 marks</p> <p align="center">02 marks for any 02 adv.</p>	
<p align="center">6</p>	<p>Attempt any four:</p>	<p align="center">4*4</p>	<p align="center">16</p>
<p>a</p>	<p>Load indicating bolts:</p> <p>(B) LOAD INDICATING (G.K.N.) SQUARE HEAD</p>  <p>As shown in the diagram above, the bolt tightening is checked with the gap present by the use of a filler gauge. Tightening is stopped when the gap is as per the manufacturer's specification.</p> <p>Load indicating washer:</p> <p>(D) USE OF INDICATING WASHER</p>  <p>The 'Coronet' load indicator is an especially hardened washer with protrusions on one face. They bear against the underside of the bolt head leaving a gap. As the bolt is tightened, the protrusions are flattened and the gap is reduced. At a specified average gap, measured by a filler</p>	<p align="center">01 mark (diag.)</p> <p align="center">01 mark (expln.)</p> <p align="center">01 mark (diag.)</p> <p align="center">01 mark (expln.)</p>	<p align="center">04</p>



	gauge, the induced shank tension should not be less than the minimum required by standards.														
b	<p>The steps in folding a sheet metal job are:</p> <ol style="list-style-type: none"> 1) Clamping: In clamping, the amount of lift of the clamping beam is important. It should be sufficient to allow the fitting and use of special clamping blades or to give adequate clearance for previous folds. 2) Folding: Care must be taken to see that the folding beam will clear the work, particularly when making second or third folds. Some folding machines are designed to fold radii above the minimum, either by the fitting of a radius bar or by adjustment of the folding beam. 3) Removal of the work: Care must be taken in folding to ensure that the work may be easily removed on completion of final board. The sequence of folding must be carefully studied. The lift of the clamping beam is important here. 	<p>01^{1/2} mark</p> <p>01^{1/2} marks</p> <p>01 mark</p>	04												
c	<p>Blanking: It is the operation of cutting of flat sheet to the desired shape. The metal punched out is the required product and the plate with the hole left on the die goes as waste. The die governs the size of the blank produced and clearance is left on the punch.</p> <p>Piercing: It is the operation of production of a hole in a sheet metal by the punch and die. The material punched out to form the hole constitutes the waste. The punch governs the size of the hole (punch point diameter is less than or equal to material thickness) and clearance is provided on die.</p>	<p>02 mark</p> <p>02 mark</p>	04												
d	<table border="1" style="width: 100%; border-collapse: collapse; margin-bottom: 10px;"> <thead> <tr> <th style="width: 30%;">Parameters</th> <th style="width: 35%;">Reciprocating Power Hacksaw</th> <th style="width: 35%;">Bench Saw</th> </tr> </thead> <tbody> <tr> <td>Cost of machine</td> <td>High capital investment</td> <td>Low capital investment.</td> </tr> <tr> <td>Sawing time</td> <td>Less time</td> <td>More time</td> </tr> <tr> <td>Labor skill</td> <td>Semi-skilled.</td> <td>Unskilled</td> </tr> </tbody> </table>	Parameters	Reciprocating Power Hacksaw	Bench Saw	Cost of machine	High capital investment	Low capital investment.	Sawing time	Less time	More time	Labor skill	Semi-skilled.	Unskilled	<p>01^{1/2} marks</p> <p>01^{1/2} mark</p> <p>01 mark</p>	04
Parameters	Reciprocating Power Hacksaw	Bench Saw													
Cost of machine	High capital investment	Low capital investment.													
Sawing time	Less time	More time													
Labor skill	Semi-skilled.	Unskilled													

<p>e</p>	<p>Technique of starting a cut away from the edge (or procedure for burning a hole)</p>	<p>02 marks for sketches</p> <p>And</p> <p>02 marks (for the points as in sketch)</p>	<p>04</p>
<p>f</p>	<p>Effect of clearance and rake angle on blades:</p> <p>Rake Angle: The shear blades are provided with a rake angle of 3° (approx.) and an optimum rake angle enables the blades to dig into the material, thereby subjecting the internal fibres of the metal to plastic deformation prior to shearing. Too much of the rake angle weakens the blades and too little a rake angle requires more force to initiate plastic deformation.</p> <p>Clearance: There must be sufficient clearance between the cutting edges of the blades to help in the cutting action. An approximate rule is that the clearance should not exceed 10% of the thickness to be cut and must be varied to suit the particular material.</p>	<p>02 marks</p> <p>02 marks</p>	<p>04</p>