

17530

11819

3 Hours / 100 Marks

Seat No.

--	--	--	--	--	--	--	--

- Instructions* – (1) All Questions are *Compulsory*.
- (2) Illustrate your answers with neat sketches wherever necessary.
- (3) Figures to the right indicate full marks.
- (4) Assume suitable data, if necessary.
- (5) Use of Non-programmable Electronic Pocket Calculator is permissible.
- (6) Mobile Phone, Pager and any other Electronic Communication devices are not permissible in Examination Hall.
- (7) Use of Steam tables, logarithmic, Mollier's chart is permitted.

Marks

1. a) **Attempt any THREE of the following:** **12**
- (i) Define metrology and state its four objectives.
- (ii) Differentiate between comparator and measuring instrument. (atleast four points)
- (iii) State Taylor's principle of gauge design with example.
- (iv) Define mean, mode, median and standard deviation.
- b) **Attempt any ONE of the following:** **6**
- (i) Differentiate between line standard, end standard and wavelength standard (atleast six points with example)
- (ii) Classify control charts and explain procedure to draw any one of them.

P.T.O.

- 2. Attempt any FOUR of the following:** **16**
- a) Draw a labelled diagram of gear tooth vernier calliper.
 - b) Explain why sine bar is not used for measurement of angle greater than 45° .
 - c) Explain relation between 'cost of quality' and 'value of quality' with the help of graph.
 - d) State the methodology of six sigma improvement and explain any one of them.
 - e) Enlist any four factors affecting accuracy of instruments.
- 3. Attempt any FOUR of the following:** **16**
- a) Draw the labelled sketch and write the stepwise procedure for squareness testing of drilling machine spindle with table.
 - b) An angle of $121^\circ 36' 27''$ is to be developed using angle gauge set of ($1^\circ, 3^\circ, 9^\circ, 27^\circ, 41^\circ$) ($1', 3', 9', 27'$) and ($3'', 6'', 18'', 30''$) with a square block. Show the arrangement with neat sketch using minimum number of gauges.
 - c) Interpret the meaning of 35H6f8 with respect to fit and basis of system.
 - d) Enlist errors in gears. Explain any one of them with neat sketch.
 - e) With respect to surface texture explain primary and secondary texture.
- 4. a) Attempt any THREE of the following:** **12**
- (i) Explain measurement of tooth thickness by constant chord method.
 - (ii) Prepare a neat labelled diagram to designate surface finish on drawing.

- (iii) State the importance of “Quality audit”
- (iv) State different types of sampling plans and explain any one of them.

b) **Attempt any ONE of the following:** **6**

- (i) Draw labelled sketch of Sigma Comparator and write its advantages. (Any three)
- (ii) Derive equation for two wire method to calculate effective diameter of screw thread.

5. **Attempt any TWO of the following:** **16**

- a) Sketch ideal and actual O.C. curve showing all parameters on it and define them.
- b) In a manufacturing process following observations are recorded:
Draw appropriate control charts and conclude.

Observation Table :

Sample No.	Defective found out of 50
1	4
2	5
3	0
4	3
5	2
6	5
7	1
8	6

- c) Write advantages and limitations of ISO 9000 (Four each).

6. **Attempt any TWO of the following:** **16**

- a) (i) Explain process capability, $\pm 3\sigma$ (Sigma)
- (ii) Draw screw thread profile and show all elements on it.
- b) Explain the terms:
 - (i) Straightness
 - (ii) Wringing of slip gauges
 - (iii) Pitch of screw thread
 - (iv) Tolerance

17530

[4]

Marks

- c) The values of $\Sigma \bar{X}$ and ΣR for a process for 20 subgroups of 5 samples are 3596.2 and 196 respectively. Specification limits for processes are 171 ± 11 . Determine the control limits for \bar{X} and R charts. Take $A_2 = 0.577$, $D_3 = 0$, $D_4 = 2.11$)
-